




10. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER



LINE CONDUCTED BACK PHOTO



END OF REPORT