



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

June 20, 2006

RE: Telematics Wireless Ltd.

FCC ID: NTAXMETER50

After a review of the submitted information for FCC, I have a few comments on the above referenced Application.

FCC Review

- 1) I do not understand how the -2.37 and -1.13 dB correction factors were calculated. Correction factors for 8-12 % would normally be 17-22 dB. From information in the report, it appears that the duty factors based upon 100 msec would be in this case $20 \log (4.3/9.8) = -7.15 \text{ dB}$ and $20 \log (3.6/10.650) = -9.42 \text{ dB}$. Additionally this does not appear to match the 12 and 13% or 8 and 9% cited. Information on pages 6, 18, 19, 20 may still be incorrect. Please review/correct/explain.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.