RUBICOM SYSTEMS, INC.

FCC TEST REPORT

(INTENTIONAL RADIATOR)

FOR THE

ROCKWELL COLLINS, INC.

VHF-4000 COMMUNICATIONS TRANSCEIVER

(118-137MHz)



Rubicom Systems, Inc. 284 West Drive, Suite B Melbourne, FL 32904 THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE WRITTEN APPROVAL OF THE TESTING LABORATORY

FCC TEST REPORT

(INTENTIONAL RADIATOR)

FOR THE

ROCKWELL COLLINS, INC.

VHF-4000 COMMUNICATIONS TRANSCEIVER


(118-137MHz)

S/N: FBLF


PART 2

| Prepared by: | | |
|--|-------------------|---|
| | Joseph G. Barbee | |
| Tested by: | Alex Belardinelli | |
| Performed by: | | Performed for: |
| RUBICOM SYSTEMS, INC. 284 West Drive, Suite B Melbourne, Florida 32904 | | ROCKWELL COLLINS, INC 1100 W. Hibiscus Blvd. Melbourne, Florida 32901 |
| Received: | September 9, 2001 | |


Completed: September 12, 2001



DATA SHEET 6.1-4



DATA SHEET 6.1-5



DATA SHEET 6.1-6