



5MHz_Low_QPSK_1@0 -24.67dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:28:47

5MHz_Low_QPSK_25@0 -24.18dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:29:17

5MHz_Middle_QPSK_1@0 -24.76dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:29:49

5MHz_Middle_QPSK_25@0 -24.55dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:30:22

5MHz_High_QPSK_1@0 -23.76dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:30:53

5MHz_High_QPSK_25@0 -24.59dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:31:24

10MHz_Low_QPSK_1@0 -24.79dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:31:59

10MHz_Low_QPSK_50@0 -24.44dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:32:30

10MHz_Middle_QPSK_1@0 -23.94dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:33:02

10MHz_Middle_QPSK_50@0 -23.82dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:33:32

10MHz_High_QPSK_1@0 -24.61dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:35:33

10MHz_High_QPSK_50@0 -24.31dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:36:03

15MHz_Low_QPSK_1@0 -24.17dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:36:37

15MHz_Low_QPSK_75@0 -23.96dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:37:06

15MHz_Middle_QPSK_1@0 -24.77dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:31:10

15MHz_Middle_QPSK_75@0 -24.24dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:38:06

15MHz_High_QPSK_1@0 -24.50dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:38:43

15MHz_High_QPSK_75@0 -24.46dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:39:14

20MHz_Low_QPSK_1@0 -25.05dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:39:50

20MHz_Low_QPSK_100@0 -24.39dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:40:24

20MHz_Middle_QPSK_1@0 -24.65dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:40:59

20MHz_Middle_QPSK_100@0 -24.52dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:41:32

20MHz_High_QPSK_1@0 -24.52dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:42:05

20MHz_High_QPSK_100@0 -25.08dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:42:38