

## LINKSYS LLC

Date: 2017/03/27

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Subject: Request to change in Identification

To Whom It May Concern:

This application for Change of Identification request a new FCC ID as stipulated in 47CFR 2.933(b) for presently authorized equipment.

This application by LINKSYS LLC will establish a new FCC ID under FCC ID: Q87-RE6350 for the purpose of marketing.

The original grant to LINKSYS LLC FCC ID: Q87-RE6250 will remain in effect.

Per 2.933(b)

- 1) The original identification is FCC ID: Q87-RE6250
- 2) The original grant date is March, 24, 2017.
- 3) The equipment is electrically and functionally identical. Only the model name, software and FCC ID number are different. The original model RE6250 disabled 11ac 2SS MCS 8 & 9 modes, the new model RE6350 enable these two modes.
- 4) The original test results are applicable and representative of this changed device
- 5) Exterior photographs are included in this application.

Applicant: LINKSYS LLC

Address: 121 Theory Drive, Irvine, California, United States

Signature:



Name and Title: James Huang

Email: james.huang@belkin.com

Tel: 949-265-1429