
















ANT L_802.11ax_HE20_52T_High_UNII 1






ANT L_802.11ax_HE20_52T_High_UNII 2A






ANT L_802.11ax_HE20_52T_High_UNII 2C







ANT L_802.11ax_HE20_52T_High_UNII 3






ANT R_802.11ax_HE20_52T_High_UNII 1






ANT R_802.11ax_HE20_52T_High_UNII 2A






ANT R_802.11ax_HE20_52T_High_UNII 2C







ANT R_802.11ax_HE20_52T_High_UNII 3






ANT L_802.11ax_HE20_106T_Low_UNII 1






ANT L_802.11ax_HE20_106T_Low_UNII 2A






ANT L_802.11ax_HE20_106T_Low_UNII 2C



ANT L_802.11ax_HE20_106T_Low_UNII 3



ANT R_802.11ax_HE20_106T_Low_UNII 1







ANT R_802.11ax_HE20_106T_Low_UNII 2A






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-01326
Page (253) / (539) Pages






ANT R_802.11ax_HE20_106T_Low_UNII 2C







ANT R_802.11ax_HE20_106T_Low_UNII 3






ANT L_802.11ax_HE20_106T_High_UNII 1






ANT L_802.11ax_HE20_106T_High_UNII 2A






ANT L_802.11ax_HE20_106T_High_UNII 2C



ANT L_802.11ax_HE20_106T_High_UNII 3



ANT R_802.11ax_HE20_106T_High_UNII 1







ANT R_802.11ax_HE20_106T_High_UNII 2A






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-01326
Page (257) / (539) Pages






ANT R_802.11ax_HE20_106T_High_UNII 2C







ANT R_802.11ax_HE20_106T_High_UNII 3






ANT L_802.11ax_HE20_242T_UNII 1






ANT L_802.11ax_HE20_242T_UNII 2A






ANT L_802.11ax_HE20_242T_UNII 2C







ANT L_802.11ax_HE20_242T_UNII 3






ANT R_802.11ax_HE20_242T_UNII 1





ANT R_802.11ax_HE20_242T_UNII 2A





ANT R_802.11ax_HE20_242T_UNII 2C







ANT R_802.11ax_HE20_242T_UNII 3



ANT L_802.11n_HT40_UNII 1



ANT L_802.11n_HT40_UNII 2A





ANT L_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (263) / (539) Pages







ANT L_802.11n_HT40_UNII 3



ANT R_802.11n_HT40_UNII 1



ANT R_802.11n_HT40_UNII 2A





ANT R_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (265) / (539) Pages







ANT R_802.11n_HT40_UNII 3



ANT L_802.11ac_VHT40_UNII 1



ANT L_802.11ac_VHT40_UNII 2A





ANT L_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (267) / (539) Pages







ANT L_802.11ac_VHT40_UNII 3



ANT R_802.11ac_VHT40_UNII 1



ANT R_802.11ac_VHT40_UNII 2A





ANT R_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-01326
Page (269) / (539) Pages



ANT R_802.11ac_VHT40_UNII 3