

To: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>  
 Cc: ellis@adt.com.tw,  
 vivi@adt.com.tw  
 Subject: =?big5?B?  
 pl6rSKFHIFJldmldyBvZiBBc2tleSBDb21wdXRlciBDb3JwLiwgRkNDIEIEOiA=?=  
 =?us-ascii?Q?H9NWLL030M?= Permissive Change

Tim,

Did we answer your attached question ?

for (2), I confirm that the ferrite will be fixed by shrink wrap. And it  
 will be done  
 by the module manufacturer.

Did you get the answer for your question (1) ??

Best Regards,

Dr. Alan Lane  
 Tel: +886 3 3270910  
 Fax: +886 3 3270892

"Timothy R.  
 Johnson" |~¥óαH¡G ellis@adt.com.tw,  
 vivi@adt.com.tw  
 <tjohnson@Americ °Æ¥»§Û°e¡G  
 Alan\_Lane@mail.adt.com.tw  
 anTCB.com> ¥D!®¡G Review of Askey Computer Corp., FCC ID:  
 H9NWLL030M Permissive  
 Change  
 2003/01/08 05:51  
 AM

Ellis/Vivi,

Attached are comments regarding review of this application. Please provide  
 information as soon as possible.

Thank You,

Timothy R. Johnson  
NARTE Certified EMC Engineer  
No. EMC-002205-NE

email: tjohnson@AmericanTCB.com  
alternate email: TRJ@adelphia.net  
(See attached file: ATCB Comments\_010703.pdf)



[=big5BQVRDQiBDb21tZW50c18wMTA3MDMucGRm=1.pdf](#)