




DUT with Harness and Serial Interface





56043255XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3423/1

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

FCC ID: TBD

IC: TBD



VS9632C000YA

JOHNSON CONTROLS INTERIORS

DR6

DUT (J1850 Diff) top



JOHNSON  
CONTROLS

**!!! WARNING !!!**

Any modifications/analysis done to this part **MUST** be recorded in:

**k:\PLUS\11830-05PA\electronics\engineering\parts record.xls**

Failure to comply compromises the ability to root cause issues,  
leading to significant project delays and wasted time.

DUT (J1850 Diff) bottom



OSPA

4.8.0~~9~~

J1850  
Plain



05091004XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3423/1

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

FCC ID: TBD

IC: TBD



VS9630C003ZA

JOHNSON CONTROLS INTERIORS

DUT (J1850 Gen) top





DUT (J1850 Gen) bottom





05064013XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3283/2

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

BUS S/W REV: 1.0

FCC ID: TBD

IC: TBD



VS8734C0014A

JOHNSON CONTROLS INTERIORS

CAN

DUT (CAN) top



JOHNSON  
CONTROLS

**!!! WARNING !!!**

Any modifications/analysis done to this part **MUST** be recorded in:  
K:\PLUS\1830-05PA\electronics\engineering\parts record.xls  
Failure to comply compromises the ability to root cause issues,  
leading to significant project delays and wasted time.

DUT (CAN) bottom