

Ericsson Wireless Communications, Inc 6455 Lusk Blvd. San Diego, CA 92121-2779

Ph: (858) 332-6026 FAX: (858) 332-7388 E-mail: D.Kimball@ericsson.com

Re: FCC ID OJYJAY1

Applicant: Ericsson Wireless Communications

Correspondence Reference Number: 7812 731 Confirmation Number: EA94134 Date of Original E-Mail: 05/18/1999

June 8, 2001

Federal Communications Commission
OET Laboratory Division Electronic Filing Site
https://gullfoss.fcc.gov/prod/oet/index.html

Dear Sir or Madam:

Qualcomm, Inc. Wireless Infrastructure Division was purchased by Ericsson Wireless Communications, Inc. effective May 24, 1999. I was Qualcomm's infrastructure regulatory manager and I have transferred to Ericsson. We are requesting a change in the FCC ID for the former Qualcomm 800MHz and 1900MHz base stations and pilot beacons. The 3 character prefix is being changed from J9C (Qualcomm) to OJY (Ericsson).

This request is for FCC ID OJYJAY1, an 800MHz 3 Sector cellular base station. The design of the base stations and pilot beacons are unchanged. In addition, the manufacturing location, equipment, processes, and personal remain unchanged. However, we will be changing the branding, trade dress, and model numbers to Ericsson's corporate standards.

The following exhibits are attached, and a separate electronic submission will be made for each FCC ID.

Exhibit 1: FCC ID Change Matrix

Exhibit 2: FCC ID Label

Exhibit 3: Photograph showing location of FCC ID label

Exhibit 4: Rear View of Base Station Exhibit 5: Front View of Base Station

Sincerely,

Donald F. Kimball Regulatory Senior Staff Engineer/Manager • Page 2 June 8, 2001

Exhibit 1: FCC ID Change Matrix

| Qualcomm | Qualcomm | Original Grant | Ericsson Model | Ericsson | FCC |
|---------------|----------|----------------|------------------|----------|-----------------|
| Model Number | FCC ID | Date | Number | FCC ID | Application No. |
| Base Stations | | | | | |
| QCell 2508i | J9CJAY1 | 07/10/96 | RBS 1102 800 | OJYJAY1 | EA94134 |
| QCell 2519e | J9CJAY2 | 03/03/98 | RBS 1102 1900 | OJYJAY2 | EA94122 |
| QCell 3508i | J9CDFK2 | 02/11/98 | RBS 1103 800 | OJYDFK2 | EA94206 |
| QCell 3519i | J9CDFK1 | 06/02/98 | RBS 1103 1900 | OJYDFK1 | EA94207 |
| QCell 619e | J9CKAG4 | 04/20/99 | RBS 1106 1900 | OJYKAG4 | EA94209 |
| Pilot Beacons | | | | | |
| QCPB 800i | J9CKAG1 | 04/07/97 | CMS 11 800i | OJYKAG1 | EA94210 |
| QCPB 1900e | J9CKAG2 | 08/01/97 | CMS 11 1900e | OJYKAG2 | EA94211 |
| QCPB 800e | J9CKAG3 | 01/21/98 | CMS 11 800e | OJYKAG3 | EA94212 |

• Page 3 June 8, 2001

Attached under Separate Exhibit Type

Exhibit 2 FCC ID Label, OJYJAY1

• Page 4 June 8, 2001

Attached under Separate Exhibit Type

Exhibit 3 FCC ID Label Location, OJYJAY1

• Page 5 June 8, 2001

Attached under Separate Exhibit Type

Exhibit 4 Rear View, OJYJAY1

• Page 6 June 8, 2001

Attached under Separate Exhibit Type

Exhibit 5 Front View, OJYJAY1