



3390 East Harmony Road  
Fort Collins  
Colorado 80528  
United States

To whom it may concern:

This device with FCC ID: B94HNI42CTKR integrates a WWAN module:

|             | Brand   | FCC ID       | Date of Grant |
|-------------|---------|--------------|---------------|
| WWAN module | Foxconn | 2AQ68T99W175 | 06/04/2020    |

No hardware design changes are made on the module, and the software has not been changed to increase the RF output power of the module and provided host level antenna gain is less than the original module grant. Pursuant to KDB 996369 D02, the original modular report (Report Number details see below) are submitted to represent the compliance of Part 22/24/27/90/96 conducted/radiated testing items of this device. Worst radiated cases found in module level testing are performed on the host level to ensure the compliance is kept.

| Modular Test Report Number |                 |                 |                 |                 |
|----------------------------|-----------------|-----------------|-----------------|-----------------|
| RF200109E02                | RF200109E02-1   | RF200109E02-2   | RF200109E02-3   | RF200109E02-4   |
| RF200109E02-5              | RF200109E02-6   | RF200109E02-7   | RF200109E02-8   | RF200109E02-9   |
| RF200109E02-10             | RF200109E02-11  | RF200109E02-12  | RF200109E02-13  | RF200109E02-14  |
| RF200109E02A-2             | RF200109E02B    | RF200109E02B-1  | RF200109E02B-2  | RF200109E02B-3  |
| RF200109E02B-4             | RF200109E02B-5  | RF200109E02B-6  | RF200109E02B-7  | RF200109E02B-8  |
| RF200109E02B-9             | RF200109E02B-10 | RF200109E02B-11 | RF200109E02B-12 | RF200109E02B-13 |
| RF200109E02B-15            |                 |                 |                 |                 |

Sincerely,

*Liang Rong Chiao*

Liang Rong Chiao

Worldwide Technical Regulations

HP Inc.

10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan

[frances.liang@hp.com](mailto:frances.liang@hp.com)

T +886-2-37892469