


ADB10EYAN, ADB10EYKN

FCC/IC LABEL Information

Hyundai MOBIS Co., Ltd.	
FCC ID:	TQ8-ADB10EYAN
IC:	5074A-ADB10EYKN
IC MODEL:	ADB10EYKN
<hr/>	
<p>This device complies with part 15 of the FCC rules Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p>	
<hr/>	
MANUFACTURED BY HYUNDAI MOBIS	

PRODUCT LABEL

LABEL LOCATION




ADB30EYAN

FCC LABEL Information

Hyundai MOBIS Co., Ltd.	
FCC ID:	TQ8-ADB10EYAN
Contains FCC ID: YZP-VL3010	
<hr/>	
<p>This device complies with part 15 of the FCC rules Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p>	
<hr/>	
MANUFACTURED BY HYUNDAI MOBIS	

PRODUCT LABEL

LABEL LOCATION



ADB30EYKN

IC LABEL Information

Hyundai MOBIS Co., Ltd.	
IC:	5074A-ADB10EYKN
IC MODEL:	ADB10EYKN
Contains IC:	7414C-BK1110
<hr/>	
<p>This device complies with part 15 of the FCC rules Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p>	
<hr/>	
MANUFACTURED BY HYUNDAI MOBIS	

PRODUCT LABEL

LABEL LOCATION

