



Suite 230  
2891 Sunridge Way NE  
Calgary, Alberta  
Canada T1Y 7K7  
Tel (403) 777-3760  
Fax (403) 777-3769  
[www.mentoreng.com](http://www.mentoreng.com)

Federal Communication Commission  
Equipment Authorization Division, Application Processing Branch  
7435 Oakland Mills Road  
Columbia, MD 21048

January 25, 2005

TO WHOM IT MAY CONCERN

Mentor Engineering's models: MultiConnect 1xRTT and BBx 1xRTT have a built-in dual band CDMA modem which is in all hardware and software aspects identical (unmodified) to the previously certified device FCC ID: RZ3MDC0V01 used in the model MDC 1xRTT. Therefore, the test results prepared by Intertek from test report 30693501 issued on 12/27/04 are applicable to the models MultiConnect 1xRTT and BBx 1xRTT.

Sincerely,

A handwritten signature in blue ink, appearing to read "S. Hickle", with a stylized flourish at the end.

Stephen Hickle  
Director

---

Mentor Engineering Inc.  
Suite 503, 609-14th Street N.W.  
Calgary, AB. Canada T2N 2A1  
Ph:(403) 777-3760 (ext 826) Fax:(403) 777-3769  
E-mail: [shickle@mentoreng.com](mailto:shickle@mentoreng.com)  
Website: [www.mentoreng.com](http://www.mentoreng.com)

### MDC Family Attributes

attribute	MDC	MultiConnect	BBX
RF module	FCC ID: 09EQ2438F	FCC ID: 09EQ2438F	FCC ID: 09EQ2438F
Display	LCD	LED	LED
Enclosure	plastic	plastic	plastic
Ports	Smart Card, PC Card, 4 COM	COM	USB, COM
GPS	yes	no	yes
Memory	Flash, RAM	no	Flash, SDRAM
I/O	Digital, Analog, Odometer	no	Digital, Analog, Odometer
Interfaces	optional J-1708, J-1850	no	optional J-1708