

Response to E04-000094-2

1. An updated manual and confidentiality letter have been uploaded with the revised FCC ID number.
2. A revised test report has been uploaded with additional information regarding the frequency stability.
3. A revised test report has been uploaded with additional information regarding this issue.