

Helen Zhao

Subject: FW: RE: FW: MIPRO ELECTRONICS CO., LTD., FCC ID: M5XMT801A, Assessment NO.: AN06T5998, Notice#1



Exhibit-J-Conf_Lett
er_rev.pdf



Exhibit-C-Test_Rep
ort_rev.2.pd...



Exhibit-D-ID_Label_
rev.pdf



Exhibit-F-Setup_Ph
otos_rev.2.p...



Exhibit-H-External_
Photos_rev....



Exhibit-B-Internal_p
hotos_rev....

From: iris

Sent: Tuesday, August 01, 2006 1:09 AM

To: Helen Zhao

Subject: Re: FW: MIPRO ELECTRONICS CO., LTD., FCC ID: M5XMT801A,
Assessment NO.: AN06T5998, Notice#1

Dear Helen,

Pls find the revised documents as attachment.

Best Regards,

Iris Lin

-----Original Message-----

From: Helen Zhao

Sent: Friday, July 28, 2006 6:11 PM

To: Helen Zhao

Subject: MIPRO ELECTRONICS CO., LTD., FCC ID: M5XMT801A, Assessment
NO.:
AN06T5998, Notice#1

Question #1: Based upon FCC2.926(d), "The equipment product code assigned by the grantee shall consist of a series of Arabic numerals, capital letters or a combination thereof, and may include the dash or hyphen (-). " Please note lower case is not allowed. Please revise FCC ID label format. Please also revise other documents in the filing that show incorrect FCC ID, e.g. test report, setup photos, external photos, internal photos, confidentiality letter.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

