

## American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

August 21, 2006

RE: Sunrex Technology Corporation

FCC ID: J750511

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The label for this transmitter should not contain the FCC logo. FCC logo only applies to computers and computer peripherals which qualify under the DofC authorization procedure. Devices which connect to a computer wirelessly and without any cable do not qualify as a computer peripheral and do not qualify for the FCC logo. On the other hand, the USB receiver will qualify as a computer peripheral and the FCC logo may apply. Please refer to 15.19(b), 15.101, 2.906, 2.909, 2.1072..
- 2.) Was this device tested in three orthogonal planes as required by ANSI C63.4?
- 3.) Please note that the method for determining the -20dB correction factor applied to the radiated test results is incorrect. Please refer to 15.35, especially 15.35(b) and (c). You should have compared the transmit on-time to 10msec, not the 36.1msec as shown in your report.

William H. Graff

President and Director of Engineering

William

mailto: whgraff@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.