



Intertek Testing Services

ETL SEMKO

Report No.: 0008502
Mode: Talk

Tested By: Hong, Report No.: 0008502


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0008502
Mode: Talk

Tested By: Hong, Report No.: 0008502

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF 60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.53000	29.7	48.0
0.59000	27.3	48.0
0.98000	19.5	48.0
1.25500	20.4	48.0
1.29500	20.2	48.0

* limit exceeded