



n71_15MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@0 -33.74dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:37:58

n71_15MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@78 -33.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:38:24

n71_15MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB75@0 -33.99dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:40:13

n71_15MHz_15kHz_690.5MHz_DFT-s-OFDM
QPSK_RB1@0 -30.92dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:42:48

n71_15MHz_15kHz_690.5MHz_DFT-s-OFDM
QPSK_RB1@78 -30.01dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:45:17

n71_15MHz_15kHz_690.5MHz_DFT-s-OFDM
QPSK_RB75@0 -34.50dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:48:14

n71_20MHz_15kHz_673MHz_DFT-s-OFDM
QPSK_RB100@0 -33.23dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaste: Liang
Date: 17.DEC.2024 19:53:36

n71_20MHz_15kHz_673MHz_DFT-s-OFDM
QPSK_RB1@0 -34.74dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaste: Liang
Date: 17.DEC.2024 15:49:10

n71_20MHz_15kHz_673MHz_DFT-s-OFDM
QPSK_RB1@105 -34.25dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaste: Liang
Date: 17.DEC.2024 19:51:00

n71_20MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB100@0 -32.31dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaste: Liang
Date: 17.DEC.2024 15:59:06

n71_20MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@0 -34.05dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaste: Liang
Date: 17.DEC.2024 19:56:34

n71_20MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@105 -29.12dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaste: Liang
Date: 17.DEC.2024 15:58:25

n71_20MHz_15kHz_688MHz_DFT-s-OFDM
QPSK_RB100@0 -29.77dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 20:01:14


n71_20MHz_15kHz_688MHz_DFT-s-OFDM
QPSK_RB1@0 -34.15dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 20:00:18


n77_1

n71_20MHz_15kHz_688MHz_DFT-s-OFDM
QPSK_RB1@105 -33.13dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 20:00:43

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -37.90dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 7.DEC.2024 10:54:36

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -38.13dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 7.DEC.2024 10:55:28

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -37.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 7.DEC.2024 10:56:21

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.83dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 7 DEC 2024 10:57:17

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -37.59dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 7 DEC 2024 10:58:09

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -38.40dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 7 DEC 2024 10:59:01

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -38.27dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 7 DEC 2024 10:59:57

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -38.25dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 7 DEC 2024 11:00:50

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -38.22dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 7 DEC 2024 11:01:42

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.18dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC. 2024 11:02:42

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.56dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC. 2024 11:03:34

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.61dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC. 2024 11:04:26

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.28dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC. 2024 11:05:26

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -37.84dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC. 2024 11:06:18

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -37.76dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC. 2024 11:07:10

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.40dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7.DEC.2024 11:08:17

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.86dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7.DEC.2024 11:09:10

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.87dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7.DEC.2024 11:10:02

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -38.08dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7.DEC.2024 11:11:03

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -36.93dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7.DEC.2024 11:11:56

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -38.49dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7.DEC.2024 11:12:48

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.45dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 7 DEC 2024 11:13:49

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -38.03dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 7 DEC 2024 11:14:42

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -38.04dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 7 DEC 2024 11:15:34

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -38.31dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 7 DEC 2024 11:16:33

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -38.30dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 7 DEC 2024 11:17:26

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -38.11dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 7 DEC 2024 11:18:18

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -38.17dBm




ProjectNo.: 2401Z104805E-RF Testert:Rungfunaster: Liang
Date: 7.DEC.2024 11:19:19

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -37.67dBm




ProjectNo.: 2401Z104805E-RF Testert:Rungfunaster: Liang
Date: 7.DEC.2024 11:20:13

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -38.09dBm




ProjectNo.: 2401Z104805E-RF Testert:Rungfunaster: Liang
Date: 7.DEC.2024 11:21:06

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.45dBm




ProjectNo.: 2401Z104805E-RF Testert:Rungfunaster: Liang
Date: 7.DEC.2024 11:22:06

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -38.20dBm




ProjectNo.: 2401Z104805E-RF Testert:Rungfunaster: Liang
Date: 7.DEC.2024 11:23:00

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -38.10dBm




ProjectNo.: 2401Z104805E-RF Testert:Rungfunaster: Liang
Date: 7.DEC.2024 11:23:52

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -38.02dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister: Liang
Date: 7.DEC.2024 11:24:52

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -38.15dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister: Liang
Date: 7.DEC.2024 11:25:46

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -38.06dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister: Liang
Date: 7.DEC.2024 11:26:39

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -38.21dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister: Liang
Date: 7.DEC.2024 11:29:32

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -38.04dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister: Liang
Date: 7.DEC.2024 11:27:45

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -37.98dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister: Liang
Date: 7.DEC.2024 11:28:39

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -38.10dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 12:58:55

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.14dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 12:57:00

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -38.38dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 12:57:58

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -38.24dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:01:56

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -38.05dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:00:00

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -37.48dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:00:58

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -37.97dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:05:01

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -37.82dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:03:04

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -38.26dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:04:04

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -37.74dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:08:05

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.09dBm



ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:06:06

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -38.08dBm



ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:07:06