

From: S. S. Liou [ssliou@seed.net.tw]
Sent: Thursday, July 17, 2003 3:02 AM
To: Mike Kuo
Subject: Re: MIPRO ELECTRONICS CO., LTD., FCC ID: M5X-707HM, Assessment
NO.: AN03T3057

Hello Mike,

Ans. #1: Please refer to attached file "Main_PCB.pdf".
Ans. #2: The emission designator is 146KF3E ($2M+2DK = 2 \times 32.768 + 2 \times 40 \times 1 = 145.5\text{kHz}$)
Ans. #3: Please refer to attached file "Tune_up_Part_list.pdf".

Best regards,

S. S. Liou
Engineer / EMC Dep. II
ETC

----- Original Message -----

From: "Mike Kuo" <MKUO@CCSEMC.com>
To: "ETC/Iris (E-mail)" <etcemi@seed.net.tw>; "Will Yauo (E-mail)"
<willyauo@seed.net.tw>; "'S. S. Liou'" <ssliou@seed.net.tw>
Sent: Tuesday, July 15, 2003 3:35 PM
Subject: FW: MIPRO ELECTRONICS CO., LTD., FCC ID: M5X-707HM, Assessment NO.:
AN03T3057

>
>
> -----Original Message-----
> From: Compliance Certification Services [mailto:MKuo@ccsemc.com]
> Sent: Monday, July 14, 2003 11:24 PM
> Subject: MIPRO ELECTRONICS CO., LTD., FCC ID: M5X-707HM, Assessment NO.:
> AN03T3057
>
>
> Question #1: Please provide additional internal photos by removing the
metal
> plate.
>
> Question #2: Please provide emission designator and justify necessary
> bandwidth by using carson rules ($2M+2DK$).
>
> Question #3: Please provide tune up procedures and parts list.
>
> Best Regards
>
> Mike Kuo
>
> The items indicated above must be submitted before processing can continue
> on the above referenced application. Failure to provide the requested
> information within 60 days of the original e-mail date may result in
> application dismissal and forfeiture of the filing fee. Also, please note
> that partial responses increase processing time and should not be
submitted.
> Any questions about the content of this correspondence should be directed
to

> the e-mail address listed below the name of the sender.