



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

May 2, 2004

RE: FCC ID: O7J-GP0000100C02\_ATCB001306  
Attention: Ellis Wu

I have a few comments on this Application.

1. Please note that the SAR report 1 section 6.1 and SAR report 4 states that a 2450MHz dipole model number D2450V2 was used for the system check / system validation. Please note that SAR report 1 section 6.3 states that the frequency of validation and system check was 1900MHz. The proper dipole at this frequency is the D1900V2 as stated in the dipole kit information on page 7 of SAR report 1 rev2. Please note that if the 2450MHz dipole model D2450V2 was used during a system check or validation at 1900MHz the test was performed incorrectly. Please provide evidence, consistent data and equipment information to validate report results. This would include properly listing the dipole used and providing the proper dipole calibration certificates for the correct dipole used.

Dennis Ward  
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.