






Date: 8.NOV.2023 18:00:17

11AC20SISO_Ant1_5785




Date: 8.NOV.2023 18:34:45

11AC20SISO_Ant1_5825




Date: 8.NOV.2023 18:50:04


11AC40SISO_Ant1_5190




11AC40SISO_Ant1_5230



11AC40SISO_Ant1_5270




11AC40SISO_Ant1_5310




Date: 6.NOV.2023 16:34:34

11AC40SISO_Ant1_5510




Date: 6.NOV.2023 16:38:25

11AC40SISO_Ant1_5550




Date: 6.NOV.2023 16:42:17

11AC40SISO_Ant1_5670




Date: 6.NOV.2023 16:44:40

11AC40SISO_Ant1_5755




Date: 8.NOV.2023 18:43:11

11AC40SISO_Ant1_5795




Date: 8.NOV.2023 18:52:07

11AX20SISO_Ant1_5180




Date: 8.NOV.2023 14:02:35

11AX20SISO_Ant1_5200




Date: 8.NOV.2023 14:09:51

11AX20SISO_Ant1_5240




Date: 8.NOV.2023 14:15:31

11AX20SISO_Ant1_5260




Date: 8.NOV.2023 14:21:23

11AX20SISO_Ant1_5280




Date: 8.NOV.2023 14:37:29

11AX20SISO_Ant1_5320




Date: 8.NOV.2023 14:43:00

11AX20SISO_Ant1_5500




Date: 8.NOV.2023 14:50:01

11AX20SISO_Ant1_5580




Date: 8.NOV.2023 15:02:21

11AX20SISO_Ant1_5700




Date: 8.NOV.2023 15:08:27


11AX20SISO_Ant1_5745




11AX20SISO_Ant1_5785



11AX20SISO_Ant1_5825




11AX40SISO_Ant1_5190




Date: 8.NOV.2023 15:15:29

11AX40SISO_Ant1_5230




Date: 8.NOV.2023 15:22:40

11AX40SISO_Ant1_5270




Date: 8.NOV.2023 15:28:36


11AX40SISO_Ant1_5310




11AX40SISO_Ant1_5510




11AX40SISO_Ant1_5550




11AX40SISO_Ant1_5670



11AX40SISO_Ant1_5755



11AX40SISO_Ant1_5795



-----End of the report-----