

Icom Inc.

1-6-19, Kamikuratsukuri, Hirano-ku, Osaka Japan. Phone: +81 6 6793 8424 Fax: +81 6 6793 3336 e-mail: world\_support@icom.co.jp

e-mail: world\_support@icom.co.jp URL: http://www.icom.co.jp/world

Date: April 4, 2018

## **To Whom It May Concern**

Subject:

**Attestation Letter** 

Applicant:

Icom Incorporated

Product:

**UHF** transceiver

Model:

IC-F6121D, IC-F6220D

FCC ID:

AFJ333211

Dear Sir/Madam,

For Part 90 frequency user, the radio is disabled 25kHz mode by radio firmware at factory in order to comply with FCC mandate for part 90 frequencies.

Best regards

Icom Incorporated

Atsushi Tomiyama General Manager of Quality Assurance Department

A. Toniyana