



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

September 19, 2004

RE: FCC ID: AB6NT1900MFRM_ATCB001718
Attention: Thomas Wong

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the plots of the OBW on pages 23 through 25, 31, 32, 36, 37, 41 and 42 in the report "Exhibit 2A - Test Report from Nortel (IS95).pdf" are not clear. While the tabular data is sufficient, when plots are provided the information needs to be clearly identifiable. Consequently, the values cannot be distinguished. Please provide plots of the OBW that are legible.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.