



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

June 4, 2005

RE: Sercomm Corporation

FCC ID: P27CB801AS

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The SAR statement on page 2 of the manual is incorrect. Kindly see the SAR report results or consult with the SAR testing laboratory for proper language. Please review and correct.
- 2.) The frequency band listed in section 2.2 of the Manual is incorrect. Please review and correct.
- 3.) Since a SAR report is provided, there is no need to include an MPE report for this device inside the Test Report. Please review and remove.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.