



HERMON LABORATORIES

September 13, 2006

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
Attn: Mr. Timothy Johnson, Examining Engineer

RE: your e-mail dated September 10, 2006; Airspan Networks Ltd.  
**FCC ID: PIDASMAX58, ATCB003949**

Dear Mr. Johnson,  
Please find below the answers to your questions.

- 1) The photograph 9 was added, the exhibit "Internal\_photos\_17234\_rev1" was uploaded on September 13, 2006.
- 2) The label was corrected, the file "Label\_location\_17234\_rev1" was uploaded on September 13, 2006
- 3) The new photographs, file "External\_photos\_17234\_rev1" was uploaded on September 13, 2006. The photographs 1, 2, 3 in "Internal\_photos\_17234\_rev1" were changed.
- 4) The adjusted file "RF\_evaluation\_17234\_rev1" was uploaded on September 13, 2006.
- 5) You are right, the provided schematics were not correct. New files, "Schematic\_diagram\_17234\_rev1" and "Confidentiality\_letter\_17234\_rev1" were uploaded on September 13, 2006.
- 6) The corrected "User\_Manual\_17234\_rev1" was uploaded on September 13, 2006.

Thank you for your assistance and support.

Sincerely,

Marina Cherniavsky,  
certification engineer  
Hermon Laboratories