




PSD NVNT n20 5300MHz Ant1




PSD NVNT n20 5320MHz Ant1




PSD NVNT n20 5500MHz Ant1




PSD NVNT n20 5600MHz Ant1



PSD NVNT n20 5700MHz Ant1




PSD NVNT n20 5745MHz Ant1




PSD NVNT n20 5785MHz Ant1




PSD NVNT n20 5825MHz Ant1




PSD NVNT n40 5190MHz Ant1




PSD NVNT n40 5230MHz Ant1




PSD NVNT n40 5270MHz Ant1




PSD NVNT n40 5310MHz Ant1




PSD NVNT n40 5510MHz Ant1




PSD NVNT n40 5590MHz Ant1




PSD NVNT n40 5670MHz Ant1




PSD NVNT n40 5755MHz Ant1




PSD NVNT n40 5795MHz Ant1




PSD NVNT ac20 5180MHz Ant1




PSD NVNT ac20 5200MHz Ant1




PSD NVNT ac20 5240MHz Ant1




PSD NVNT ac20 5260MHz Ant1




PSD NVNT ac20 5300MHz Ant1




PSD NVNT ac20 5320MHz Ant1




PSD NVNT ac20 5500MHz Ant1



PSD NVNT ac20 5600MHz Ant1




PSD NVNT ac20 5700MHz Ant1




PSD NVNT ac20 5745MHz Ant1




PSD NVNT ac20 5785MHz Ant1



PSD NVNT ac20 5825MHz Ant1




PSD NVNT ac40 5190MHz Ant1




PSD NVNT ac40 5230MHz Ant1




PSD NVNT ac40 5270MHz Ant1




PSD NVNT ac40 5310MHz Ant1




PSD NVNT ac40 5510MHz Ant1



PSD NVNT ac40 5590MHz Ant1



PSD NVNT ac40 5670MHz Ant1




PSD NVNT ac40 5755MHz Ant1




PSD NVNT ac40 5795MHz Ant1




PSD NVNT ac80 5210MHz Ant1




PSD NVNT ac80 5290MHz Ant1




PSD NVNT ac80 5530MHz Ant1



PSD NVNT ac80 5610MHz Ant1



PSD NVNT ac80 5775MHz Ant1



Frequency Stability

Condition	Mode	Time (mins)	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
20C 2.81V	a	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 3.30V	a	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 3.80V	a	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
0C 3.30V	a	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
10C 3.30V	a	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
30C 3.30V	a	0	5180	Ant1	5179.98	-20000	-3.86	25	Pass
40C 3.30V	a	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
50C 3.30V	a	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 2.81V	a	0	5200	Ant1	5199.94	-60000	-11.54	25	Pass
20C 3.30V	a	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
20C 3.80V	a	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
0C 3.30V	a	0	5200	Ant1	5199.94	-60000	-11.54	25	Pass
10C 3.30V	a	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
30C 3.30V	a	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
40C 3.30V	a	0	5200	Ant1	5199.98	-20000	-3.85	25	Pass
50C 3.30V	a	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
20C 2.81V	a	0	5240	Ant1	5239.98	-20000	-3.82	25	Pass
20C 3.30V	a	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
20C 3.80V	a	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
0C 3.30V	a	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass

10C 3.30V	a	0	5240	Ant1	5239.94	-60000	-11.45	25	Pass
30C 3.30V	a	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
40C 3.30V	a	0	5240	Ant1	5239.98	-20000	-3.82	25	Pass
50C 3.30V	a	0	5240	Ant1	5239.98	-20000	-3.82	25	Pass
NVNT	a	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
20C 2.81V	a	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
20C 3.30V	a	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
20C 3.80V	a	0	5300	Ant1	5299.94	-60000	-11.32	25	Pass
0C 3.30V	a	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
10C 3.30V	a	0	5300	Ant1	5299.94	-60000	-11.32	25	Pass
30C 3.30V	a	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
40C 3.30V	a	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
50C 3.30V	a	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
20C 2.81V	a	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
20C 3.30V	a	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
20C 3.80V	a	0	5320	Ant1	5319.94	-60000	-11.28	25	Pass
0C 3.30V	a	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
10C 3.30V	a	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
30C 3.30V	a	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
40C 3.30V	a	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
50C 3.30V	a	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
20C 2.81V	a	0	5500	Ant1	5499.94	-60000	-10.91	25	Pass
20C	a	0	5500	Ant1	5499.94	-60000	-10.91	25	Pass

3.30V									
20C 3.80V	a	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
0C 3.30V	a	0	5500	Ant1	5499.94	-60000	-10.91	25	Pass
10C 3.30V	a	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
30C 3.30V	a	0	5500	Ant1	5499.94	-60000	-10.91	25	Pass
40C 3.30V	a	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
50C 3.30V	a	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
20C 2.81V	a	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 3.30V	a	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 3.80V	a	0	5600	Ant1	5599.94	-60000	-10.71	25	Pass
0C 3.30V	a	0	5600	Ant1	5599.94	-60000	-10.71	25	Pass
10C 3.30V	a	0	5600	Ant1	5599.94	-60000	-10.71	25	Pass
30C 3.30V	a	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
40C 3.30V	a	0	5600	Ant1	5599.94	-60000	-10.71	25	Pass
50C 3.30V	a	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 2.81V	a	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
20C 3.30V	a	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
20C 3.80V	a	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
0C 3.30V	a	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
10C 3.30V	a	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
30C 3.30V	a	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
40C 3.30V	a	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
50C 3.30V	a	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass

20C 2.81V	a	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
20C 3.30V	a	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
20C 3.80V	a	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
0C 3.30V	a	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
10C 3.30V	a	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
30C 3.30V	a	0	5745	Ant1	5744.96	-40000	-6.96	25	Pass
40C 3.30V	a	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
50C 3.30V	a	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
20C 2.81V	a	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
20C 3.30V	a	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
20C 3.80V	a	0	5785	Ant1	5784.94	-60000	-10.37	25	Pass
0C 3.30V	a	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
10C 3.30V	a	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
30C 3.30V	a	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
40C 3.30V	a	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
50C 3.30V	a	0	5785	Ant1	5784.94	-60000	-10.37	25	Pass
20C 2.81V	a	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
20C 3.30V	a	0	5825	Ant1	5824.94	-60000	-10.3	25	Pass
20C 3.80V	a	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
0C 3.30V	a	0	5825	Ant1	5824.94	-60000	-10.3	25	Pass
10C 3.30V	a	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
30C 3.30V	a	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
40C	a	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass

3.30V									
50C 3.30V	a	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
20C 2.81V	n20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 3.30V	n20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 3.80V	n20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
0C 3.30V	n20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
10C 3.30V	n20	0	5180	Ant1	5179.98	-20000	-3.86	25	Pass
30C 3.30V	n20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
40C 3.30V	n20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
50C 3.30V	n20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 2.81V	n20	0	5200	Ant1	5199.98	-20000	-3.85	25	Pass
20C 3.30V	n20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
20C 3.80V	n20	0	5200	Ant1	5199.98	-20000	-3.85	25	Pass
0C 3.30V	n20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
10C 3.30V	n20	0	5200	Ant1	5199.94	-60000	-11.54	25	Pass
30C 3.30V	n20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
40C 3.30V	n20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
50C 3.30V	n20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
20C 2.81V	n20	0	5240	Ant1	5239.94	-60000	-11.45	25	Pass
20C 3.30V	n20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
20C 3.80V	n20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
0C 3.30V	n20	0	5240	Ant1	5239.98	-20000	-3.82	25	Pass
10C 3.30V	n20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass

30C 3.30V	n20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
40C 3.30V	n20	0	5240	Ant1	5239.94	-60000	-11.45	25	Pass
50C 3.30V	n20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
20C 2.81V	n20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
20C 3.30V	n20	0	5260	Ant1	5259.94	-60000	-11.41	25	Pass
20C 3.80V	n20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
0C 3.30V	n20	0	5260	Ant1	5259.98	-20000	-3.8	25	Pass
10C 3.30V	n20	0	5260	Ant1	5259.94	-60000	-11.41	25	Pass
30C 3.30V	n20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
40C 3.30V	n20	0	5260	Ant1	5259.94	-60000	-11.41	25	Pass
50C 3.30V	n20	0	5260	Ant1	5259.94	-60000	-11.41	25	Pass
20C 2.81V	n20	0	5300	Ant1	5299.94	-60000	-11.32	25	Pass
20C 3.30V	n20	0	5300	Ant1	5299.98	-20000	-3.77	25	Pass
20C 3.80V	n20	0	5300	Ant1	5299.98	-20000	-3.77	25	Pass
0C 3.30V	n20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
10C 3.30V	n20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
30C 3.30V	n20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
40C 3.30V	n20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
50C 3.30V	n20	0	5300	Ant1	5299.98	-20000	-3.77	25	Pass
20C 2.81V	n20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
20C 3.30V	n20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
20C 3.80V	n20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass

0C 3.30V	n20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
10C 3.30V	n20	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
30C 3.30V	n20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
40C 3.30V	n20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
50C 3.30V	n20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
20C 2.81V	n20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
20C 3.30V	n20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
20C 3.80V	n20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
0C 3.30V	n20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
10C 3.30V	n20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
30C 3.30V	n20	0	5500	Ant1	5499.94	-60000	-10.91	25	Pass
40C 3.30V	n20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
50C 3.30V	n20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
20C 2.81V	n20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 3.30V	n20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 3.80V	n20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
0C 3.30V	n20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
10C 3.30V	n20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
30C 3.30V	n20	0	5600	Ant1	5599.98	-20000	-3.57	25	Pass
40C 3.30V	n20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
50C 3.30V	n20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 2.81V	n20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
20C	n20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass

3.30V									
20C 3.80V	n20	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
0C 3.30V	n20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
10C 3.30V	n20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
30C 3.30V	n20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
40C 3.30V	n20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
50C 3.30V	n20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
20C 2.81V	n20	0	5745	Ant1	5744.96	-40000	-6.96	25	Pass
20C 3.30V	n20	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
20C 3.80V	n20	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
0C 3.30V	n20	0	5745	Ant1	5744.96	-40000	-6.96	25	Pass
10C 3.30V	n20	0	5745	Ant1	5744.96	-40000	-6.96	25	Pass
30C 3.30V	n20	0	5745	Ant1	5744.96	-40000	-6.96	25	Pass
40C 3.30V	n20	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
50C 3.30V	n20	0	5745	Ant1	5744.96	-40000	-6.96	25	Pass
20C 2.81V	n20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
20C 3.30V	n20	0	5785	Ant1	5784.94	-60000	-10.37	25	Pass
20C 3.80V	n20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
0C 3.30V	n20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
10C 3.30V	n20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
30C 3.30V	n20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
40C 3.30V	n20	0	5785	Ant1	5784.94	-60000	-10.37	25	Pass
50C 3.30V	n20	0	5785	Ant1	5784.94	-60000	-10.37	25	Pass

20C 2.81V	n20	0	5825	Ant1	5824.94	-60000	-10.3	25	Pass
20C 3.30V	n20	0	5825	Ant1	5824.94	-60000	-10.3	25	Pass
20C 3.80V	n20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
0C 3.30V	n20	0	5825	Ant1	5824.94	-60000	-10.3	25	Pass
10C 3.30V	n20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
30C 3.30V	n20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
40C 3.30V	n20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
50C 3.30V	n20	0	5825	Ant1	5824.98	-20000	-3.43	25	Pass
20C 2.81V	n40	0	5190	Ant1	5190	0	0	25	Pass
20C 3.30V	n40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
20C 3.80V	n40	0	5190	Ant1	5190	0	0	25	Pass
0C 3.30V	n40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
10C 3.30V	n40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
30C 3.30V	n40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
40C 3.30V	n40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
50C 3.30V	n40	0	5190	Ant1	5190	0	0	25	Pass
20C 2.81V	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
20C 3.30V	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
20C 3.80V	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
0C 3.30V	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
10C 3.30V	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
30C 3.30V	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
40C	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass

3.30V									
50C 3.30V	n40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
20C 2.81V	n40	0	5270	Ant1	5270	0	0	25	Pass
20C 3.30V	n40	0	5270	Ant1	5270	0	0	25	Pass
20C 3.80V	n40	0	5270	Ant1	5270	0	0	25	Pass
0C 3.30V	n40	0	5270	Ant1	5270	0	0	25	Pass
10C 3.30V	n40	0	5270	Ant1	5269.96	-40000	-7.59	25	Pass
30C 3.30V	n40	0	5270	Ant1	5269.96	-40000	-7.59	25	Pass
40C 3.30V	n40	0	5270	Ant1	5270	0	0	25	Pass
50C 3.30V	n40	0	5270	Ant1	5270	0	0	25	Pass
20C 2.81V	n40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
20C 3.30V	n40	0	5310	Ant1	5309.92	-80000	-15.07	25	Pass
20C 3.80V	n40	0	5310	Ant1	5309.92	-80000	-15.07	25	Pass
0C 3.30V	n40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
10C 3.30V	n40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
30C 3.30V	n40	0	5310	Ant1	5309.92	-80000	-15.07	25	Pass
40C 3.30V	n40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
50C 3.30V	n40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
20C 2.81V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
20C 3.30V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
20C 3.80V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
0C 3.30V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
10C 3.30V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass

30C 3.30V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
40C 3.30V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
50C 3.30V	n40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
20C 2.81V	n40	0	5590	Ant1	5590	0	0	25	Pass
20C 3.30V	n40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
20C 3.80V	n40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
0C 3.30V	n40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
10C 3.30V	n40	0	5590	Ant1	5590	0	0	25	Pass
30C 3.30V	n40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
40C 3.30V	n40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
50C 3.30V	n40	0	5590	Ant1	5589.92	-80000	-14.31	25	Pass
20C 2.81V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
20C 3.30V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
20C 3.80V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
0C 3.30V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
10C 3.30V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
30C 3.30V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
40C 3.30V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
50C 3.30V	n40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
20C 2.81V	n40	0	5755	Ant1	5754.96	-40000	-6.95	25	Pass
20C 3.30V	n40	0	5755	Ant1	5754.96	-40000	-6.95	25	Pass
20C 3.80V	n40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass

0C 3.30V	n40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
10C 3.30V	n40	0	5755	Ant1	5754.96	-40000	-6.95	25	Pass
30C 3.30V	n40	0	5755	Ant1	5754.96	-40000	-6.95	25	Pass
40C 3.30V	n40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
50C 3.30V	n40	0	5755	Ant1	5754.96	-40000	-6.95	25	Pass
20C 2.81V	n40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
20C 3.30V	n40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
20C 3.80V	n40	0	5795	Ant1	5794.92	-80000	-13.81	25	Pass
0C 3.30V	n40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
10C 3.30V	n40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
30C 3.30V	n40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
40C 3.30V	n40	0	5795	Ant1	5795	0	0	25	Pass
50C 3.30V	n40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
20C 2.81V	ac20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 3.30V	ac20	0	5180	Ant1	5179.94	-60000	-11.58	25	Pass
20C 3.80V	ac20	0	5180	Ant1	5179.94	-60000	-11.58	25	Pass
0C 3.30V	ac20	0	5180	Ant1	5179.92	-80000	-15.44	25	Pass
10C 3.30V	ac20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
30C 3.30V	ac20	0	5180	Ant1	5179.94	-60000	-11.58	25	Pass
40C 3.30V	ac20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
50C 3.30V	ac20	0	5180	Ant1	5179.96	-40000	-7.72	25	Pass
20C 2.81V	ac20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
20C	ac20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass

3.30V									
20C 3.80V	ac20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
0C 3.30V	ac20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
10C 3.30V	ac20	0	5200	Ant1	5199.98	-20000	-3.85	25	Pass
30C 3.30V	ac20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
40C 3.30V	ac20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
50C 3.30V	ac20	0	5200	Ant1	5199.96	-40000	-7.69	25	Pass
20C 2.81V	ac20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
20C 3.30V	ac20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
20C 3.80V	ac20	0	5240	Ant1	5239.94	-60000	-11.45	25	Pass
0C 3.30V	ac20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
10C 3.30V	ac20	0	5240	Ant1	5239.94	-60000	-11.45	25	Pass
30C 3.30V	ac20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
40C 3.30V	ac20	0	5240	Ant1	5239.98	-20000	-3.82	25	Pass
50C 3.30V	ac20	0	5240	Ant1	5239.96	-40000	-7.63	25	Pass
20C 2.81V	ac20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
20C 3.30V	ac20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
20C 3.80V	ac20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
0C 3.30V	ac20	0	5260	Ant1	5259.98	-20000	-3.8	25	Pass
10C 3.30V	ac20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
30C 3.30V	ac20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
40C 3.30V	ac20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass
50C 3.30V	ac20	0	5260	Ant1	5259.96	-40000	-7.6	25	Pass

20C 2.81V	ac20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
20C 3.30V	ac20	0	5300	Ant1	5299.98	-20000	-3.77	25	Pass
20C 3.80V	ac20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
0C 3.30V	ac20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
10C 3.30V	ac20	0	5300	Ant1	5299.96	-40000	-7.55	25	Pass
30C 3.30V	ac20	0	5300	Ant1	5299.98	-20000	-3.77	25	Pass
40C 3.30V	ac20	0	5300	Ant1	5299.94	-60000	-11.32	25	Pass
50C 3.30V	ac20	0	5300	Ant1	5299.94	-60000	-11.32	25	Pass
20C 2.81V	ac20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
20C 3.30V	ac20	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
20C 3.80V	ac20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
0C 3.30V	ac20	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
10C 3.30V	ac20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
30C 3.30V	ac20	0	5320	Ant1	5319.98	-20000	-3.76	25	Pass
40C 3.30V	ac20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
50C 3.30V	ac20	0	5320	Ant1	5319.96	-40000	-7.52	25	Pass
20C 2.81V	ac20	0	5500	Ant1	5499.98	-20000	-3.64	25	Pass
20C 3.30V	ac20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
20C 3.80V	ac20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
0C 3.30V	ac20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
10C 3.30V	ac20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
30C 3.30V	ac20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
40C	ac20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass

3.30V									
50C 3.30V	ac20	0	5500	Ant1	5499.96	-40000	-7.27	25	Pass
20C 2.81V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 3.30V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 3.80V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
0C 3.30V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
10C 3.30V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
30C 3.30V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
40C 3.30V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
50C 3.30V	ac20	0	5600	Ant1	5599.96	-40000	-7.14	25	Pass
20C 2.81V	ac20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
20C 3.30V	ac20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
20C 3.80V	ac20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
0C 3.30V	ac20	0	5700	Ant1	5699.96	-40000	-7.02	25	Pass
10C 3.30V	ac20	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
30C 3.30V	ac20	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
40C 3.30V	ac20	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
50C 3.30V	ac20	0	5700	Ant1	5699.94	-60000	-10.53	25	Pass
20C 2.81V	ac20	0	5745	Ant1	5744.92	-80000	-13.93	25	Pass
20C 3.30V	ac20	0	5745	Ant1	5744.96	-40000	-6.96	25	Pass
20C 3.80V	ac20	0	5745	Ant1	5744.92	-80000	-13.93	25	Pass
0C 3.30V	ac20	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
10C 3.30V	ac20	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass

30C 3.30V	ac20	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
40C 3.30V	ac20	0	5745	Ant1	5744.94	-60000	-10.44	25	Pass
50C 3.30V	ac20	0	5745	Ant1	5744.98	-20000	-3.48	25	Pass
20C 2.81V	ac20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
20C 3.30V	ac20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
20C 3.80V	ac20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
0C 3.30V	ac20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
10C 3.30V	ac20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
30C 3.30V	ac20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
40C 3.30V	ac20	0	5785	Ant1	5784.98	-20000	-3.46	25	Pass
50C 3.30V	ac20	0	5785	Ant1	5784.96	-40000	-6.91	25	Pass
20C 2.81V	ac20	0	5825	Ant1	5824.98	-20000	-3.43	25	Pass
20C 3.30V	ac20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
20C 3.80V	ac20	0	5825	Ant1	5824.98	-20000	-3.43	25	Pass
0C 3.30V	ac20	0	5825	Ant1	5824.94	-60000	-10.3	25	Pass
10C 3.30V	ac20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
30C 3.30V	ac20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
40C 3.30V	ac20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
50C 3.30V	ac20	0	5825	Ant1	5824.96	-40000	-6.87	25	Pass
20C 2.81V	ac40	0	5190	Ant1	5190	0	0	25	Pass
20C 3.30V	ac40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
20C 3.80V	ac40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass

0C 3.30V	ac40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
10C 3.30V	ac40	0	5190	Ant1	5190	0	0	25	Pass
30C 3.30V	ac40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
40C 3.30V	ac40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
50C 3.30V	ac40	0	5190	Ant1	5189.96	-40000	-7.71	25	Pass
20C 2.81V	ac40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
20C 3.30V	ac40	0	5230	Ant1	5229.92	-80000	-15.3	25	Pass
20C 3.80V	ac40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
0C 3.30V	ac40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
10C 3.30V	ac40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
30C 3.30V	ac40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
40C 3.30V	ac40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
50C 3.30V	ac40	0	5230	Ant1	5229.96	-40000	-7.65	25	Pass
20C 2.81V	ac40	0	5270	Ant1	5270	0	0	25	Pass
20C 3.30V	ac40	0	5270	Ant1	5270	0	0	25	Pass
20C 3.80V	ac40	0	5270	Ant1	5269.96	-40000	-7.59	25	Pass
0C 3.30V	ac40	0	5270	Ant1	5269.96	-40000	-7.59	25	Pass
10C 3.30V	ac40	0	5270	Ant1	5269.96	-40000	-7.59	25	Pass
30C 3.30V	ac40	0	5270	Ant1	5270	0	0	25	Pass
40C 3.30V	ac40	0	5270	Ant1	5270	0	0	25	Pass
50C 3.30V	ac40	0	5270	Ant1	5269.96	-40000	-7.59	25	Pass
20C 2.81V	ac40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
20C	ac40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass

3.30V									
20C 3.80V	ac40	0	5310	Ant1	5309.92	-80000	-15.07	25	Pass
0C 3.30V	ac40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
10C 3.30V	ac40	0	5310	Ant1	5309.92	-80000	-15.07	25	Pass
30C 3.30V	ac40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
40C 3.30V	ac40	0	5310	Ant1	5309.96	-40000	-7.53	25	Pass
50C 3.30V	ac40	0	5310	Ant1	5309.92	-80000	-15.07	25	Pass
20C 2.81V	ac40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
20C 3.30V	ac40	0	5510	Ant1	5509.92	-80000	-14.52	25	Pass
20C 3.80V	ac40	0	5510	Ant1	5509.92	-80000	-14.52	25	Pass
0C 3.30V	ac40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
10C 3.30V	ac40	0	5510	Ant1	5509.92	-80000	-14.52	25	Pass
30C 3.30V	ac40	0	5510	Ant1	5509.92	-80000	-14.52	25	Pass
40C 3.30V	ac40	0	5510	Ant1	5509.92	-80000	-14.52	25	Pass
50C 3.30V	ac40	0	5510	Ant1	5509.96	-40000	-7.26	25	Pass
20C 2.81V	ac40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
20C 3.30V	ac40	0	5590	Ant1	5589.92	-80000	-14.31	25	Pass
20C 3.80V	ac40	0	5590	Ant1	5589.92	-80000	-14.31	25	Pass
0C 3.30V	ac40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
10C 3.30V	ac40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
30C 3.30V	ac40	0	5590	Ant1	5590	0	0	25	Pass
40C 3.30V	ac40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass
50C 3.30V	ac40	0	5590	Ant1	5589.96	-40000	-7.16	25	Pass

20C 2.81V	ac40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
20C 3.30V	ac40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
20C 3.80V	ac40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
0C 3.30V	ac40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
10C 3.30V	ac40	0	5670	Ant1	5669.92	-80000	-14.11	25	Pass
30C 3.30V	ac40	0	5670	Ant1	5669.92	-80000	-14.11	25	Pass
40C 3.30V	ac40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
50C 3.30V	ac40	0	5670	Ant1	5669.96	-40000	-7.05	25	Pass
20C 2.81V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
20C 3.30V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
20C 3.80V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
0C 3.30V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
10C 3.30V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
30C 3.30V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
40C 3.30V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
50C 3.30V	ac40	0	5755	Ant1	5754.92	-80000	-13.9	25	Pass
20C 2.81V	ac40	0	5795	Ant1	5794.92	-80000	-13.81	25	Pass
20C 3.30V	ac40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
20C 3.80V	ac40	0	5795	Ant1	5794.92	-80000	-13.81	25	Pass
0C 3.30V	ac40	0	5795	Ant1	5794.92	-80000	-13.81	25	Pass
10C 3.30V	ac40	0	5795	Ant1	5794.92	-80000	-13.81	25	Pass
30C 3.30V	ac40	0	5795	Ant1	5794.92	-80000	-13.81	25	Pass
40C	ac40	0	5795	Ant1	5794.92	-80000	-13.81	25	Pass

3.30V									
50C 3.30V	ac40	0	5795	Ant1	5794.96	-40000	-6.9	25	Pass
20C 2.81V	ac80	0	5210	Ant1	5210.16	160000	30.71	25	Pass
20C 3.30V	ac80	0	5210	Ant1	5210	0	0	25	Pass
20C 3.80V	ac80	0	5210	Ant1	5210	0	0	25	Pass
0C 3.30V	ac80	0	5210	Ant1	5209.92	-80000	-15.36	25	Pass
10C 3.30V	ac80	0	5210	Ant1	5210.16	160000	30.71	25	Pass
30C 3.30V	ac80	0	5210	Ant1	5210.24	240000	46.07	25	Pass
40C 3.30V	ac80	0	5210	Ant1	5210.24	240000	46.07	25	Pass
50C 3.30V	ac80	0	5210	Ant1	5210	0	0	25	Pass
20C 2.81V	ac80	0	5290	Ant1	5290	0	0	25	Pass
20C 3.30V	ac80	0	5290	Ant1	5290	0	0	25	Pass
20C 3.80V	ac80	0	5290	Ant1	5289.92	-80000	-15.12	25	Pass
0C 3.30V	ac80	0	5290	Ant1	5290	0	0	25	Pass
10C 3.30V	ac80	0	5290	Ant1	5289.92	-80000	-15.12	25	Pass
30C 3.30V	ac80	0	5290	Ant1	5289.92	-80000	-15.12	25	Pass
40C 3.30V	ac80	0	5290	Ant1	5289.92	-80000	-15.12	25	Pass
50C 3.30V	ac80	0	5290	Ant1	5289.92	-80000	-15.12	25	Pass
20C 2.81V	ac80	0	5530	Ant1	5530	0	0	25	Pass
20C 3.30V	ac80	0	5530	Ant1	5530	0	0	25	Pass
20C 3.80V	ac80	0	5530	Ant1	5530	0	0	25	Pass
0C 3.30V	ac80	0	5530	Ant1	5529.92	-80000	-14.47	25	Pass
10C 3.30V	ac80	0	5530	Ant1	5529.92	-80000	-14.47	25	Pass

30C 3.30V	ac80	0	5530	Ant1	5530	0	0	25	Pass
40C 3.30V	ac80	0	5530	Ant1	5530	0	0	25	Pass
50C 3.30V	ac80	0	5530	Ant1	5529.92	-80000	-14.47	25	Pass
20C 2.81V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
20C 3.30V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
20C 3.80V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
0C 3.30V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
10C 3.30V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
30C 3.30V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
40C 3.30V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
50C 3.30V	ac80	0	5610	Ant1	5609.92	-80000	-14.26	25	Pass
20C 2.81V	ac80	0	5775	Ant1	5775	0	0	25	Pass
20C 3.30V	ac80	0	5775	Ant1	5775	0	0	25	Pass
20C 3.80V	ac80	0	5775	Ant1	5775	0	0	25	Pass
0C 3.30V	ac80	0	5775	Ant1	5774.92	-80000	-13.85	25	Pass
10C 3.30V	ac80	0	5775	Ant1	5775	0	0	25	Pass
30C 3.30V	ac80	0	5775	Ant1	5775.08	80000	13.85	25	Pass
40C 3.30V	ac80	0	5775	Ant1	5775.08	80000	13.85	25	Pass
50C 3.30V	ac80	0	5775	Ant1	5775	0	0	25	Pass

-6dB Bandwidth

Condition	Mode	Frequency (MHz)	Antenna	-6 dB Bandwidth (MHz)	Limit -6 dB Bandwidth (MHz)	Verdict
NVNT	a	5745	Ant1	16.33	0.5	Pass
NVNT	a	5785	Ant1	16.31	0.5	Pass
NVNT	a	5825	Ant1	16.3	0.5	Pass
NVNT	n20	5745	Ant1	17.29	0.5	Pass
NVNT	n20	5785	Ant1	17.22	0.5	Pass
NVNT	n20	5825	Ant1	17.01	0.5	Pass
NVNT	n40	5755	Ant1	35.61	0.5	Pass
NVNT	n40	5795	Ant1	35.29	0.5	Pass
NVNT	ac20	5745	Ant1	17.33	0.5	Pass
NVNT	ac20	5785	Ant1	17.02	0.5	Pass
NVNT	ac20	5825	Ant1	17.27	0.5	Pass
NVNT	ac40	5755	Ant1	35.29	0.5	Pass
NVNT	ac40	5795	Ant1	35.48	0.5	Pass
NVNT	ac80	5775	Ant1	75.13	0.5	Pass

Test Graphs

-6dB Bandwidth NVNT a 5745MHz Ant1




-6dB Bandwidth NVNT a 5785MHz Ant1




-6dB Bandwidth NVNT a 5825MHz Ant1




-6dB Bandwidth NVNT n20 5745MHz Ant1




-6dB Bandwidth NVNT n20 5785MHz Ant1




-6dB Bandwidth NVNT n20 5825MHz Ant1



-6dB Bandwidth NVNT n40 5755MHz Ant1




-6dB Bandwidth NVNT n40 5795MHz Ant1



-6dB Bandwidth NVNT ac20 5745MHz Ant1




-6dB Bandwidth NVNT ac20 5785MHz Ant1




-6dB Bandwidth NVNT ac20 5825MHz Ant1



-6dB Bandwidth NVNT ac40 5755MHz Ant1



-6dB Bandwidth NVNT ac40 5795MHz Ant1



-6dB Bandwidth NVNT ac80 5775MHz Ant1

