



July 5, 2006

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD 21046

Re: FCC ID: 07KPL5161

To Whom It May Concern:

This will serve as a Class II Permissive Change request for the above mentioned FCC Identifier.

The manufacturer has changed the PLL in the transceiver because the original part is no longer available. Enclosed are the changes to the schematics, printed circuit board, and parts lists.

We have performed radiated emissions testing and there is no degradation from the original test data and there is no change in the output power. The data in the test report shows that it still continues to meet the FCC requirements for this class of equipment.

Should you have any questions or require any further information, please advise.

Regards,

A handwritten signature in black ink, reading 'Mario de Aranzeta'. The signature is written in a cursive, flowing style.

Mario de Aranzeta  
Engineer