



HERMON LABORATORIES

June 6, 2006

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated May 30, 2006; Mobile Access Networks Ltd.  
**FCC ID:OJFMA2K-IDEN-SMR, ATCB003236**

Dear Mr. Johnson,  
Please find below the answers to your questions.

- 1) The revised Users Manual (please see page 35), file "User\_guide\_16224-2\_rev1" was uploaded on June 6, 2006.
- 2) The file "RF\_exposure\_16224-2" was uploaded on June 6, 2006 via RF Exposure Info folder.
- 3) The both modulations, iDEN and SMR, were provided throughout power, conducted spurious and occupied bandwidth test. Please refer to pages 9, 30, 44 of MOBRAD\_FCC.16224-2\_rev1.  
NB! The same pages 9, 30, 44 of MOBRAD\_FCC.16224-1\_rev1 show that the both modulations, iDEN and SMR, were provided for MA1000 (1K) unit.

Sincerely,

Marina Cherniavsky,  
certification engineer  
Hermon Laboratories