


Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 1
FCC ID: P3A-LP9100




Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 2
FCC ID: P3A-LP9100



Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 3
FCC ID: P3A-LP9100




Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 4
FCC ID: P3A-LP9100



Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 5
FCC ID: P3A-LP9100




Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 6
FCC ID: P3A-LP9100



Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204


Photo # 7
FCC ID: P3A-LP9100





Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204


Photo # 9
FCC ID: P3A-LP9100





Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 11
FCC ID: P3A-LP9100



Annex 1- Photographs of Test Setup
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 12
FCC ID: P3A-LP9100

