Honeywell

Safety and Productivity Solutions
9680 Old Bailes Road
Fort Mill, SC 29707 USA
www.honeywell.com www.honeywellaidc.com

September 3, 2019

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046

Subject: Class II Permissive Change FCC ID: HD5-CK65L0N

Dear Application Examiner:

Honeywell International Inc is submitting an application for a Class II Permissive Change to permit a new RF exposure condition, in which the radios within Honeywell Model: CK65L0N (FCC ID: HD5-CK65L0N) mobile computer are co-located with the radios within Intermec Model: IP30C Handheld RFID Reader.

The IP30C contains Intermec Model: IM11 RFID radio module (FCC ID: EHA-IM11) and BlueGiga Model: WT12 Bluetooth radio module (FCC ID: QOQWT12).

The RF Exposure condition occurs when the Honeywell Model: CK65L0N mobile computer interfaces with the Intermec Model: IP30C Handheld RFID Reader. The two devices are mechanically attached and interface through Bluetooth pairing.

In this configuration, only hand-held use is possible, so MPE estimates were performed for the co-located radios. In addition to the RF Exposure report that documents compliance for body exposure, extremity SAR for the handheld use condition was evaluated in a separate test report.

No changes have been made to the hardware or software of the radios in these co-located configurations.

Your efforts in reviewing this application are greatly appreciated. Please contact me if there are questions or additional information needed concerning this request.

Sincerely,

Sean MacKellar

Product Compliance, Sr. Compliance Engineer Honeywell Safety and Productivity Solutions

See Hotelle

16201 25th Ave West Lynnwood, WA 98087 Tel: +14259214342

sean.mackellar@honeywell.com