




**SGS-CSTC Standards Technical Services Co., Ltd.**  
**Shenzhen Branch**


Report No.: ZR/2018/A000801

Page: 25 of 59


**BAND41\_15MHz\_QPSK\_41515\_75RB#0**



**BAND41\_15MHz\_64QAM\_39765\_75RB#0**



**BAND41\_15MHz\_64QAM\_40640\_75RB#0**






# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 26 of 59

## BAND41\_15MHz\_64QAM\_41515\_75RB#0




Date: 22.OCT.2018 09:14:29

## BAND41\_15MHz\_16QAM\_39765\_75RB#0



Date: 22.OCT.2018 09:10:10

## BAND41\_15MHz\_16QAM\_40640\_75RB#0



Date: 22.OCT.2018 09:12:57




# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 27 of 59

## BAND41\_15MHz\_16QAM\_41515\_75RB#0




Date: 22.OCT.2018 09:15:12

## BAND41\_20MHz\_QPSK\_39790\_100RB#0



Date: 22.OCT.2018 09:18:53

## BAND41\_20MHz\_QPSK\_40640\_100RB#0



Date: 22.OCT.2018 09:24:11




# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 28 of 59


## BAND41\_20MHz\_QPSK\_41490\_100RB#0



## BAND41\_20MHz\_64QAM\_39790\_100RB#0



## BAND41\_20MHz\_64QAM\_40640\_100RB#0






**SGS-CSTC Standards Technical Services Co., Ltd.**  
**Shenzhen Branch**


Report No.: ZR/2018/A000801

Page: 29 of 59


**BAND41\_20MHz\_64QAM\_41490\_100RB#0**



**BAND41\_20MHz\_16QAM\_39790\_100RB#0**



**BAND41\_20MHz\_16QAM\_40640\_100RB#0**






**SGS-CSTC Standards Technical Services Co., Ltd.**  
**Shenzhen Branch**

Report No.: ZR/2018/A000801

Page: 30 of 59

**BAND41\_20MHz\_16QAM\_41490\_100RB#0**




Date: 22.OCT.2018 09:26:21





## 5. Band Edge Compliance

### 5.1. Test Plots






# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 32 of 59


## BAND 41\_5MHz\_QPSK\_41565\_1RB#24



## BAND 41\_5MHz\_QPSK\_41565\_25RB#0



## BAND 41\_5MHz\_16QAM\_39715\_1RB#0








# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 33 of 59

## BAND 41\_5MHz\_16QAM\_39715\_25RB#0




Date: 22.OCT.2018 10:12:05

## BAND 41\_5MHz\_16QAM\_41565\_1RB#24



Date: 22.OCT.2018 09:51:15

## BAND 41\_5MHz\_16QAM\_41565\_25RB#0



Date: 22.OCT.2018 09:49:37




# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 34 of 59

## BAND 41\_5MHz\_64QAM\_39715\_1RB#0




Date: 22.OCT.2018 10:13:39

## BAND 41\_5MHz\_64QAM\_39715\_25RB#0



Date: 22.OCT.2018 10:12:18

## BAND 41\_5MHz\_64QAM\_41565\_1RB#24



Date: 22.OCT.2018 09:50:57




# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 35 of 59

## BAND 41\_5MHz\_64QAM\_41565\_25RB#0




Date: 22.OCT.2018 09:49:52

## BAND 41\_10MHz\_QPSK\_39740\_1RB#0



Date: 22.OCT.2018 10:20:06

## BAND 41\_10MHz\_QPSK\_39740\_50RB#0



Date: 22.OCT.2018 10:18:42




# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 36 of 59

## BAND 41\_10MHz\_QPSK\_41540\_1RB#49




Date: 22.OCT.2018 09:47:32

## BAND 41\_10MHz\_QPSK\_41540\_50RB#0



Date: 22.OCT.2018 09:45:51

## BAND 41\_10MHz\_16QAM\_39740\_1RB#0



Date: 22.OCT.2018 10:19:41






# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 37 of 59

## BAND 41\_10MHz\_16QAM\_39740\_50RB#0




Date: 22.OCT.2018 10:18:52

## BAND 41\_10MHz\_16QAM\_41540\_1RB#49



Date: 22.OCT.2018 09:47:14

## BAND 41\_10MHz\_16QAM\_41540\_50RB#0



Date: 22.OCT.2018 09:46:18




# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 38 of 59

## BAND 41\_10MHz\_64QAM\_39740\_1RB#0




Date: 22.OCT.2018 10:19:24

## BAND 41\_10MHz\_64QAM\_39740\_50RB#0



Date: 22.OCT.2018 10:19:07

## BAND 41\_10MHz\_64QAM\_41540\_1RB#49



Date: 22.OCT.2018 09:46:55






# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 39 of 59


## BAND 41\_10MHz\_64QAM\_41540\_50RB#0



## BAND 41\_15MHz\_QPSK\_39765\_1RB#0



## BAND 41\_15MHz\_QPSK\_39765\_75RB#0






# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 40 of 59


## BAND 41\_15MHz\_QPSK\_41515\_1RB#74



## BAND 41\_15MHz\_QPSK\_41515\_75RB#0



## BAND 41\_15MHz\_16QAM\_39765\_1RB#0






# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 41 of 59

## BAND 41\_15MHz\_16QAM\_39765\_75RB#0




Date: 22.OCT.2018 10:23:09

## BAND 41\_15MHz\_16QAM\_41515\_1RB#74



Date: 22.OCT.2018 09:43:10

## BAND 41\_15MHz\_16QAM\_41515\_75RB#0



Date: 22.OCT.2018 09:41:57




# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 42 of 59

## BAND 41\_15MHz\_64QAM\_39765\_1RB#0




Date: 22.OCT.2018 10:23:41

## BAND 41\_15MHz\_64QAM\_39765\_75RB#0



Date: 22.OCT.2018 10:23:26

## BAND 41\_15MHz\_64QAM\_41515\_1RB#74



Date: 22.OCT.2018 09:42:53






# SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 43 of 59

## BAND 41\_15MHz\_64QAM\_41515\_75RB#0



## BAND 41\_20MHz\_QPSK\_39790\_1RB#0



## BAND 41\_20MHz\_QPSK\_39790\_100RB#0

