

Applicant:	Benq
FCC ID#	JVP56W10
Correspondence Reference Number:	11824
731 Confirmation Number:	TC676181
Date of Original E-mail:	04/06/2004

Dear Sir,

The responses are as follows:

1)) Please describe software/firm ware provisions on the card that will prevent simultaneous transmission.

Response :

The software program has been built into the reflash/RAM inside on transmitting and the user can't access to it anyway. All setting -up procedure has done and completed on production. The users can't authorize to change the features of device even simultaneous transmission.

2) Please provide details of the GPRS capability. Number of up/down time slots.

Response :

The GPRS function is a class 10 device which can provide 2 time slots up link and 4 time slots down link, the crest factor should be 1:4 for this condition.

3) Please provide photographs of test positions and SAR contour plots. It is noted they are contained in a superceded report.

Response : This has been uploaded.

4) Please update the user manual statement to include a definition of what host devices these are allowed to operate in i.e. "substantially similar laptops".

Response:

A Revised Users Manual has been provided.

5) What is the difference between test mode 1 and 4?

Mode 1 = WLAN TX, Mode 4 = GPRS TX.

6) Please update the equipment class from PCT to PCB.

Please see Revised Grant.

7) Please update the grant to contain the highest SAR value in the band.

Please see Revised Grant.