



Ericsson Wireless Communications, Inc
6455 Lusk Blvd.
San Diego, CA 92121-2779

Ph: (619) 658-4534
FAX: (619) 658-2120
E-mail: dkimball@qualcomm.com

Re: FCC ID OJYJAY2
Applicant: Ericsson Wireless Communications
Correspondence Reference Number: 7737
731 Confirmation Number: EA94122
Date of Original E-Mail: 05/12/1999

June 15, 2001

Federal Communications Commission
OET Laboratory Division Electronic Filing Site
<<https://gulfoss.fcc.gov/prod/oet/index.html>>

Dear Sir or Madam:

Qualcomm, Inc. Wireless Infrastructure Division was purchased by Ericsson Wireless Communications, Inc. effective May 24, 1999. I was Qualcomm's infrastructure regulatory manager and I have transferred to Ericsson. We are requesting a change in the FCC ID for the former Qualcomm 800MHz and 1900MHz base stations and pilot beacons. The 3 character prefix is being changed from J9C (Qualcomm) to OJY (Ericsson).

This request is for FCC ID OJYJAY2, a 1900MHz 3 Sector cellular base station. The design of the base stations and pilot beacons are unchanged. In addition, the manufacturing location, equipment, processes, and personal remain unchanged. However, we will be changing the branding, trade dress, and model numbers to Ericsson's corporate standards.

The following exhibits are attached, and a separate electronic submission will be made for each FCC ID.

- Exhibit 1: FCC ID Change Matrix
- Exhibit 2: FCC ID Label
- Exhibit 3: Photograph showing location of FCC ID label
- Exhibit 4: Rear View of Base Station
- Exhibit 5: Front View of Base Station

Sincerely,

Donald F. Kimball
Regulatory Senior Staff Engineer/Manager

Exhibit 1: FCC ID Change Matrix

Qualcomm Model Number	Qualcomm FCC ID	Original Grant Date	Ericsson Model Number	Ericsson FCC ID	FCC Application No.
Base Stations					
QCell 2508i	J9CJAY1	07/10/96	RBS 1102 800	OJYJAY1	EA94134
QCell 2519e	J9CJAY2	03/03/98	RBS 1102 1900	OJYJAY2	EA94122
QCell 3508i	J9CDFK2	02/11/98	RBS 1103 800	OJYDFK2	EA94206
QCell 3519i	J9CDFK1	06/02/98	RBS 1103 1900	OJYDFK1	EA94207
QCell 619e	J9CKAG4	04/20/99	RBS 1106 1900	OJYKAG4	EA94209
Pilot Beacons					
QCPB 800i	J9CKAG1	04/07/97	CMS 11 800i	OJYKAG1	EA94210
QCPB 1900e	J9CKAG2	08/01/97	CMS 11 1900e	OJYKAG2	EA94211
QCPB 800e	J9CKAG3	01/21/98	CMS 11 800e	OJYKAG3	EA94212



Acrobat Document

Exhibit 2 FCC ID Label, OJYJAY2, Click to Display

FCC ID Label Location, OJYJAY2




Exhibit 3 FCC ID Label Location, OJYJAY2

FCC ID Label Location, OJYJAY2



Exhibit 4 Rear View, OJYDFK2



Exhibit 5 Front View, OJYJAY2