

5150-5250 MHz:

a_5180MHz_Chain 0




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:15:17

a 5240MHz Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng


ac20_5200MHz_Chain 0z



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:00:18


a_5200MHz_Chain 0

Report No.: 2407T76694E-RF-04




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:17:13

ac20 5180MHz Chain 0



ac20_5240MHz_Chain 0




ProjectNo.:2407T76694E-RF Tester:Stein Peng

Date: 24.MAY.2024 16:00:43


FCC Part 15.407 Page 272 of 283

ac40_5190MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:01:18


ac80_5210MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:02:15

ac40_5230MHz_Chain 0

Report No.: 2407T76694E-RF-04




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:01:46

FCC Part 15.407 Page 273 of 283


5250-5350 MHz:

a_5260MHz_Chain 0




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:21:13

a 5320MHz Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:25:57


ac20_5280MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:04:31


a_5280MHz_Chain 0

Report No.: 2407T76694E-RF-04




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:23:54

ac20 5260MHz Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:04:08


ac20_5320MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:04:56


FCC Part 15.407 Page 274 of 283

ac40_5270MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:05:28


ac80_5290MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:06:24

ac40_5310MHz_Chain 0

Report No.: 2407T76694E-RF-04




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:05:54

FCC Part 15.407 Page 275 of 283


5470-5725 MHz:


a_5500MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:29:53

a_5700MHz_Chain 0






ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:09:25

Date: 24.MAY.2024 09:34:39


a_5580MHz_Chain 0

Report No.: 2407T76694E-RF-04




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:32:12

a_5720MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:36:46


ac20_5580MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:09:45


FCC Part 15.407 Page 276 of 283

ac20_5700MHz_Chain 0




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:10:14

ac40 5510MHz Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng


ac40_5670MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:12:34


ac20_5720MHz_Chain 0

Report No.: 2407T76694E-RF-04




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:10:52

ac40 5550MHz Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:12:09

ac40_5710MHz_Chain 0




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:13:09

Date: 24.MAY.2024 16:13:09


FCC Part 15.407 Page 277 of 283

$ac80_5530MHz_Chain~0$




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:13:50

ac80_5690MHz_Chain 0



ac80_5610MHz_Chain 0

Report No.: 2407T76694E-RF-04




ProjectNo.:2407T76694E-RF Tester:Stein Peng

FCC Part 15.407 Page 278 of 283


5725-5850 MHz:

a 5745MHz_Chain 0




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:38:50

a 5825MHz Chain 0




ac20_5785MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:20:10


a_5785MHz_Chain 0

Report No.: 2407T76694E-RF-04



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 09:41:37

ac20 5745MHz Chain 0



ac20 5825MHz Chain 0




ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:20:36

Date: 24.MAY.2024 16:19:44


FCC Part 15.407 Page 279 of 283

ac $40_5755MHz$ _Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:21:16


ac80_5775MHz_Chain 0



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:22:30

ac40_5795MHz_Chain 0

Report No.: 2407T76694E-RF-04



ProjectNo.:2407T76694E-RF Tester:Stein Peng Date: 24.MAY.2024 16:21:49

FCC Part 15.407 Page 280 of 283

EUT PHOTOGRAPHS

Please refer to the attachment 2407T76694E-RF-EXP EUT EXTERNAL PHOTOGRAPHS and 2407T76694E-RF-INP EUT INTERNAL PHOTOGRAPHS.

Report No.: 2407T76694E-RF-04

FCC Part 15.407 Page 281 of 283

TEST SETUP PHOTOGRAPHS

Please refer to the attachment 2407T76694E-RF-TSP-02 SETUP PHOTOGRAPHS.

Report No.: 2407T76694E-RF-04

FCC Part 15.407 Page 282 of 283

Declarations

Report No.: 2407T76694E-RF-04

- 1. Bay Area Compliance Laboratories Corp. (Xiamen) is not responsible for authenticity of any information provided by the applicant. Information from the applicant that may affect test results are marked with an asterisk "★".
- 2. Unless otherwise stated, the results shown in this test report refer only to the sample(s) tested.
- 3. Unless required by the rule provided by the applicant or product regulations, then decision rule in this report did not consider the uncertainty.
- 4. The extended uncertainty given in this report is obtained by combining the standard uncertainty times the coverage factor k=2 with the 95% confidence interval.
- 5. This report cannot be reproduced except in full, without prior written approval of Bay Area Compliance Laboratories Corp. (Xiamen).
- 6. This report is valid only with a valid digital signature. The digital signature may be available only under the adobe software above version 7.0.

***** END OF REPORT *****

FCC Part 15.407 Page 283 of 283