


# Appendix C. Set up Photograph

## Conducted Emission

Mode 1~2



**FRONT VIEW** 



#### **REAR VIEW**

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : Mar. 10, 2006
Report Version : Rev. 01

Report No.: FR611809





SIDE VIEW

#### Mode 3




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : Mar. 10, 2006
Report Version : Rev. 01





## **REAR VIEW**



# SIDE VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : Mar. 10, 2006
Report Version : Rev. 01





# **Radiation Emission**



**FRONT VIEW** 

**REAR VIEW** 

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : Mar. 10, 2006
Report Version : Rev. 01