
Test Report No.: G0M-2302-1878-EF0115B-V01


Eurofins Product Service GmbH
Storkower Str. 38c, D-15526 Reichenwalde, Germany

Radio Report FCC 47 CFR Part 15B

TEST SETUP – CONFIGURATION 1




TEST SETUP – CONFIGURATION 2




TEST SETUP 30 – 1000 MHz - CONFIGURATION 1




TEST SETUP 1 – 13 GHz - CONFIGURATION 1



TEST SETUP 30 – 1000 MHz - CONFIGURATION 2



TEST SETUP 1 – 13 GHz - CONFIGURATION 2



TEST SETUP – AC Mains

