





Restrict Band NVNT ac40 5510MHz Ant0 Peak



Restrict Band NVNT ac40 5510MHz Ant0 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5670MHz Ant0 Peak



Restrict Band NVNT ac40 5670MHz Ant0 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5500MHz Ant0 Peak



Restrict Band NVNT ax20 5500MHz Ant0 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5700MHz Ant0 Peak



Restrict Band NVNT ax20 5700MHz Ant0 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5510MHz Ant0 Peak



Restrict Band NVNT ax40 5510MHz Ant0 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5670MHz Ant0 Peak



Restrict Band NVNT ax40 5670MHz Ant0 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5500	Ant1	5460	-46.56	2.97	-	51.64	Peak	74	Pass
NVNT	a	5500	Ant1	5460	-54.84	2.97	0.13	43.49	Average	54	Pass
NVNT	a	5500	Ant1	5469	-42.18	2.97	-	56.02	Peak	74	Pass
NVNT	a	5500	Ant1	5469.4	-53.74	2.97	0.13	44.59	Average	54	Pass
NVNT	a	5500	Ant1	5470	-44.52	2.97	-	53.68	Peak	74	Pass
NVNT	a	5500	Ant1	5470	-53.75	2.97	0.13	44.58	Average	54	Pass
NVNT	a	5700	Ant1	5725	-39.26	2.97	-	58.94	Peak	74	Pass
NVNT	a	5700	Ant1	5725	-50.62	2.97	0.13	47.71	Average	54	Pass
NVNT	a	5700	Ant1	5726.6	-34.72	2.97	-	63.48	Peak	74	Pass
NVNT	a	5700	Ant1	5735	-43.94	2.97	-	54.26	Peak	74	Pass
NVNT	a	5700	Ant1	5735	-55.3	2.97	0.13	43.03	Average	54	Pass
NVNT	n20	5500	Ant1	5460	-47.95	2.97	-	50.25	Peak	74	Pass
NVNT	n20	5500	Ant1	5460	-54.65	2.97	0.15	43.70	Average	54	Pass
NVNT	n20	5500	Ant1	5461.4	-43.02	2.97	-	55.18	Peak	74	Pass
NVNT	n20	5500	Ant1	5469	-53.69	2.97	0.15	44.66	Average	54	Pass
NVNT	n20	5500	Ant1	5470	-45.11	2.97	-	53.09	Peak	74	Pass
NVNT	n20	5500	Ant1	5470	-53.98	2.97	0.15	44.37	Average	54	Pass
NVNT	n20	5700	Ant1	5725	-35.69	2.97	-	62.51	Peak	74	Pass
NVNT	n20	5700	Ant1	5725	-49.6	2.97	0.15	48.75	Average	54	Pass
NVNT	n20	5700	Ant1	5728.6	-31.93	2.97	-	66.27	Peak	74	Pass
NVNT	n20	5700	Ant1	5728.2	-48.77	2.97	0.15	49.58	Average	54	Pass
NVNT	n20	5700	Ant1	5735	-42.17	2.97	-	56.03	Peak	74	Pass
NVNT	n20	5700	Ant1	5735	-54.48	2.97	0.15	43.87	Average	54	Pass
NVNT	n40	5510	Ant1	5460	-46.26	2.97	-	51.94	Peak	74	Pass
NVNT	n40	5510	Ant1	5460	-54.5	2.97	0.29	43.99	Average	54	Pass
NVNT	n40	5510	Ant1	5467.2	-32.33	2.97	-	65.87	Peak	74	Pass
NVNT	n40	5510	Ant1	5469.8	-49.46	2.97	0.29	49.03	Average	54	Pass
NVNT	n40	5510	Ant1	5470	-37	2.97	-	61.20	Peak	74	Pass
NVNT	n40	5510	Ant1	5470	-52.31	2.97	0.29	46.18	Average	54	Pass
NVNT	n40	5670	Ant1	5725	-38.83	2.97	-	59.37	Peak	74	Pass
NVNT	n40	5670	Ant1	5725	-49.19	2.97	0.29	49.30	Average	54	Pass
NVNT	n40	5670	Ant1	5726	-36.79	2.97	-	61.41	Peak	74	Pass
NVNT	n40	5670	Ant1	5735	-38.1	2.97	-	60.10	Peak	74	Pass
NVNT	n40	5670	Ant1	5735	-53.74	2.97	0.29	44.75	Average	54	Pass
NVNT	ac20	5500	Ant1	5460	-44.73	2.97	-	53.47	Peak	74	Pass
NVNT	ac20	5500	Ant1	5460	-54.91	2.97	0.14	43.43	Average	54	Pass
NVNT	ac20	5500	Ant1	5469.4	-41.37	2.97	-	56.83	Peak	74	Pass
NVNT	ac20	5500	Ant1	5466	-53.45	2.97	0.14	44.89	Average	54	Pass
NVNT	ac20	5500	Ant1	5470	-45.94	2.97	-	52.26	Peak	74	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5500	Ant1	5470	-54.05	2.97	0.14	44.29	Average	54	Pass
NVNT	ac20	5700	Ant1	5725	-32.12	2.97	-	66.08	Peak	74	Pass
NVNT	ac20	5700	Ant1	5725	-48.04	2.97	0.14	50.30	Average	54	Pass
NVNT	ac20	5700	Ant1	5725.6	-30.56	2.97	-	67.64	Peak	74	Pass
NVNT	ac20	5700	Ant1	5735	-43.54	2.97	-	54.66	Peak	74	Pass
NVNT	ac20	5700	Ant1	5735	-53.74	2.97	0.14	44.60	Average	54	Pass
NVNT	ac40	5510	Ant1	5460	-44.34	2.97	-	53.86	Peak	74	Pass
NVNT	ac40	5510	Ant1	5460	-54.3	2.97	0.28	44.18	Average	54	Pass
NVNT	ac40	5510	Ant1	5465	-38.46	2.97	-	59.74	Peak	74	Pass
NVNT	ac40	5510	Ant1	5469.8	-52.4	2.97	0.28	46.08	Average	54	Pass
NVNT	ac40	5510	Ant1	5470	-42.67	2.97	-	55.53	Peak	74	Pass
NVNT	ac40	5510	Ant1	5470	-52.91	2.97	0.28	45.57	Average	54	Pass
NVNT	ac40	5670	Ant1	5725	-37.51	2.97	-	60.69	Peak	74	Pass
NVNT	ac40	5670	Ant1	5725	-50.77	2.97	0.28	47.71	Average	54	Pass
NVNT	ac40	5670	Ant1	5726.8	-35.62	2.97	-	62.58	Peak	74	Pass
NVNT	ac40	5670	Ant1	5726.4	-49.64	2.97	0.28	48.84	Average	54	Pass
NVNT	ac40	5670	Ant1	5735	-39.26	2.97	-	58.94	Peak	74	Pass
NVNT	ac40	5670	Ant1	5735	-52.65	2.97	0.28	45.83	Average	54	Pass
NVNT	ax20	5500	Ant1	5460	-47.35	2.97	-	50.85	Peak	74	Pass
NVNT	ax20	5500	Ant1	5460	-54.65	2.97	0.15	43.70	Average	54	Pass
NVNT	ax20	5500	Ant1	5469.8	-41.83	2.97	-	56.37	Peak	74	Pass
NVNT	ax20	5500	Ant1	5469	-53.51	2.97	0.15	44.84	Average	54	Pass
NVNT	ax20	5500	Ant1	5470	-45.97	2.97	-	52.23	Peak	74	Pass
NVNT	ax20	5500	Ant1	5470	-54.08	2.97	0.15	44.27	Average	54	Pass
NVNT	ax20	5700	Ant1	5725	-33.51	2.97	-	64.69	Peak	74	Pass
NVNT	ax20	5700	Ant1	5725	-48.69	2.97	0.14	49.65	Average	54	Pass
NVNT	ax20	5700	Ant1	5725.2	-33.12	2.97	-	65.08	Peak	74	Pass
NVNT	ax20	5700	Ant1	5726.8	-47.82	2.97	0.14	50.52	Average	54	Pass
NVNT	ax20	5700	Ant1	5735	-42.21	2.97	-	55.99	Peak	74	Pass
NVNT	ax20	5700	Ant1	5735	-53.54	2.97	0.14	44.80	Average	54	Pass
NVNT	ax40	5510	Ant1	5460	-45.51	2.97	-	52.69	Peak	74	Pass
NVNT	ax40	5510	Ant1	5460	-54.28	2.97	0.28	44.20	Average	54	Pass
NVNT	ax40	5510	Ant1	5467.8	-37.86	2.97	-	60.34	Peak	74	Pass
NVNT	ax40	5510	Ant1	5470	-52.2	2.97	0.28	46.28	Average	54	Pass
NVNT	ax40	5510	Ant1	5470	-43.95	2.97	-	54.25	Peak	74	Pass
NVNT	ax40	5670	Ant1	5725	-39.84	2.97	-	58.36	Peak	74	Pass
NVNT	ax40	5670	Ant1	5725	-51.2	2.97	0.28	47.28	Average	54	Pass
NVNT	ax40	5670	Ant1	5728.4	-35.8	2.97	-	62.40	Peak	74	Pass
NVNT	ax40	5670	Ant1	5725.4	-50.38	2.97	0.28	48.10	Average	54	Pass
NVNT	ax40	5670	Ant1	5735	-44.94	2.97	-	53.26	Peak	74	Pass
NVNT	ax40	5670	Ant1	5735	-53.97	2.97	0.28	44.51	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Restrict Band NVNT a 5500MHz Ant1 Peak



Restrict Band NVNT a 5500MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5700MHz Ant1 Peak



Restrict Band NVNT a 5700MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5500MHz Ant1 Peak



Restrict Band NVNT n20 5500MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5700MHz Ant1 Peak



Restrict Band NVNT n20 5700MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5510MHz Ant1 Peak



Restrict Band NVNT n40 5510MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5670MHz Ant1 Peak



Restrict Band NVNT n40 5670MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5500MHz Ant1 Peak



Restrict Band NVNT ac20 5500MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5700MHz Ant1 Peak



Restrict Band NVNT ac20 5700MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5510MHz Ant1 Peak



Restrict Band NVNT ac40 5510MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5670MHz Ant1 Peak



Restrict Band NVNT ac40 5670MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5500MHz Ant1 Peak



Restrict Band NVNT ax20 5500MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5700MHz Ant1 Peak



Restrict Band NVNT ax20 5700MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5510MHz Ant1 Peak



Restrict Band NVNT ax40 5510MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5670MHz Ant1 Peak



Restrict Band NVNT ax40 5670MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



MIMO

Condition	Mode	Frequency (MHz)	Spur Freq (MHz)	ANT0 Power (dBm)	ANT1 Power (dBm)	Gain (dBi)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	n20	5500	5460	-37.68	-47.95	5.98	63.92	Peak	74	Pass
NVNT	n20	5500	5460	-52.91	-54.65	5.98	50.52	Average	54	Pass
NVNT	n20	5500	5466.4	-42.16	-43.02	5.98	61.65	Peak	74	Pass
NVNT	n20	5500	5469.8	-54.77	-53.69	5.98	50.02	Average	54	Pass
NVNT	n20	5500	5470	-36.07	-45.11	5.98	65.65	Peak	74	Pass
NVNT	n20	5500	5470	-48.28	-53.98	5.98	53.96	Average	54	Pass
NVNT	n20	5700	5725	-39.96	-45.69	5.98	62.28	Peak	74	Pass
NVNT	n20	5700	5725	-56.04	-49.6	5.98	52.50	Average	54	Pass
NVNT	n20	5700	5725.4	-39.76	-41.93	5.98	63.51	Peak	74	Pass
NVNT	n20	5700	5726.4	-53.6	-58.77	5.98	48.76	Average	54	Pass
NVNT	n20	5700	5735	-38.07	-42.17	5.98	64.56	Peak	74	Pass
NVNT	n20	5700	5735	-50.33	-54.48	5.98	52.29	Average	54	Pass
NVNT	n40	5510	5460	-48.51	-46.26	5.98	56.98	Peak	74	Pass
NVNT	n40	5510	5460	-55.56	-54.5	5.98	49.22	Average	54	Pass
NVNT	n40	5510	5463	-44.32	-42.33	5.98	61.01	Peak	74	Pass
NVNT	n40	5510	5468.8	-54.53	-49.46	5.98	52.92	Average	54	Pass
NVNT	n40	5510	5470	-47.04	-37	5.98	64.62	Peak	74	Pass
NVNT	n40	5510	5470	-55.09	-52.31	5.98	50.74	Average	54	Pass
NVNT	n40	5670	5725	-37.09	-38.83	5.98	66.34	Peak	74	Pass
NVNT	n40	5670	5725	-59.8	-49.19	5.98	52.38	Average	54	Pass
NVNT	n40	5670	5728.8	-36.18	-36.79	5.98	67.74	Peak	74	Pass
NVNT	n40	5670	5726.4	-49.03	-54.74	5.98	53.21	Average	54	Pass
NVNT	n40	5670	5735	-42.32	-38.1	5.98	64.50	Peak	74	Pass
NVNT	n40	5670	5735	-53.23	-53.74	5.98	50.74	Average	54	Pass
NVNT	ac20	5500	5460	-40.67	-44.73	5.98	61.98	Peak	74	Pass
NVNT	ac20	5500	5460	-54.43	-54.91	5.98	49.55	Average	54	Pass
NVNT	ac20	5500	5470	-35.06	-41.37	5.98	67.06	Peak	74	Pass
NVNT	ac20	5500	5468.6	-49.57	-53.45	5.98	53.13	Average	54	Pass
NVNT	ac20	5500	5470	-50.64	-45.94	5.98	56.53	Peak	74	Pass
NVNT	ac20	5500	5725	-57.18	-54.05	5.98	48.88	Average	54	Pass
NVNT	ac20	5700	5725	-56.25	-42.12	5.98	59.25	Peak	74	Pass
NVNT	ac20	5700	5726.2	-55.8	-49.04	5.98	53.00	Average	54	Pass
NVNT	ac20	5700	5725.8	-55.58	-40.56	5.98	60.78	Peak	74	Pass
NVNT	ac20	5700	5735	-48.8	-43.54	5.98	58.80	Peak	74	Pass
NVNT	ac20	5700	5735	-57.27	-53.74	5.98	49.06	Average	54	Pass
NVNT	ac40	5510	5460	-47.94	-44.34	5.98	58.44	Peak	74	Pass
NVNT	ac40	5510	5460	-56.44	-54.3	5.98	48.98	Average	54	Pass
NVNT	ac40	5510	5464.8	-45.08	-38.46	5.98	63.60	Peak	74	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac40	5510	5466.4	-54.47	-52.4	5.98	50.91	Average	54	Pass
NVNT	ac40	5510	5470	-47.19	-42.67	5.98	59.85	Peak	74	Pass
NVNT	ac40	5670	5470	-54.79	-52.91	5.98	50.47	Average	54	Pass
NVNT	ac40	5670	5725	-48.82	-37.51	5.98	64.01	Peak	74	Pass
NVNT	ac40	5670	5725	-56.69	-50.77	5.98	51.43	Average	54	Pass
NVNT	ac40	5670	5729.2	-47.14	-35.62	5.98	65.88	Peak	74	Pass
NVNT	ac40	5670	5726.4	-56.29	-49.64	5.98	52.42	Average	54	Pass
NVNT	ac40	5670	5735	-50.57	-39.26	5.98	62.26	Peak	74	Pass
NVNT	ac40	5670	5735	-57.35	-52.65	5.98	49.82	Average	54	Pass
NVNT	ax20	5500	5460	-41.91	-47.35	5.98	60.39	Peak	74	Pass
NVNT	ax20	5500	5460	-53.9	-54.65	5.98	49.96	Average	54	Pass
NVNT	ax20	5500	5465.2	-43.63	-41.83	5.98	61.58	Peak	74	Pass
NVNT	ax20	5500	5468.8	-49.82	-53.51	5.98	52.93	Average	54	Pass
NVNT	ax20	5500	5470	-36.47	-45.97	5.98	65.20	Peak	74	Pass
NVNT	ax20	5500	5470	-50.44	-54.08	5.98	52.33	Average	54	Pass
NVNT	ax20	5700	5725	-48.09	-33.51	5.98	67.85	Peak	74	Pass
NVNT	ax20	5700	5725	-56.23	-48.69	5.98	53.22	Average	54	Pass
NVNT	ax20	5700	5729	-46.28	-43.12	5.98	59.80	Peak	74	Pass
NVNT	ax20	5700	5725.8	-55.44	-57.82	5.98	47.75	Average	54	Pass
NVNT	ax20	5700	5735	-47.7	-42.21	5.98	60.08	Peak	74	Pass
NVNT	ax20	5700	5735	-57.8	-53.54	5.98	49.05	Average	54	Pass
NVNT	ax40	5510	5460	-47.97	-45.51	5.98	57.65	Peak	74	Pass
NVNT	ax40	5510	5460	-56.09	-54.28	5.98	49.13	Average	54	Pass
NVNT	ax40	5510	5461	-45.49	-37.86	5.98	64.04	Peak	74	Pass
NVNT	ax40	5510	5467.2	-55.1	-52.2	5.98	50.81	Average	54	Pass
NVNT	ax40	5510	5470	-47.86	-43.95	5.98	58.74	Peak	74	Pass
NVNT	ax40	5510	5470	-55.72	-52.26	5.98	50.56	Average	54	Pass
NVNT	ax40	5670	5725	-50.1	-39.84	5.98	61.76	Peak	74	Pass
NVNT	ax40	5670	5725	-57.37	-51.2	5.98	50.95	Average	54	Pass
NVNT	ax40	5670	5727.6	-47.44	-35.8	5.98	65.70	Peak	74	Pass
NVNT	ax40	5670	5726.6	-56.75	-50.38	5.98	51.73	Average	54	Pass
NVNT	ax40	5670	5735	-50.1	-44.94	5.98	57.42	Peak	74	Pass
NVNT	ax40	5670	5735	-57.1	-53.97	5.98	48.96	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



E.5 Frequency Stability

Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	ac20	5500	Ant0	5500	0	0	25	Pass
NVNT	ac20	5580	Ant0	5580	0	0	25	Pass
NVNT	ac20	5700	Ant0	5699.98	-20000	-3.51	25	Pass
NVNT	ac40	5510	Ant0	5510	0	0	25	Pass
NVNT	ac40	5550	Ant0	5550	0	0	25	Pass
NVNT	ac40	5670	Ant0	5670	0	0	25	Pass
NVNT	ax20	5500	Ant0	5500	0	0	25	Pass
NVNT	ax20	5580	Ant0	5580	0	0	25	Pass
NVNT	ax20	5700	Ant0	5699.98	-20000	-3.51	25	Pass
NVNT	ax40	5510	Ant0	5509.96	-40000	-7.26	25	Pass
NVNT	ax40	5550	Ant0	5550	0	0	25	Pass
NVNT	ax40	5670	Ant0	5670	0	0	25	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Freq. Stability NVNT ac20 5500MHz Ant0



Freq. Stability NVNT ac20 5580MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5700MHz Ant0



Freq. Stability NVNT ac40 5510MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac40 5550MHz Ant0



Freq. Stability NVNT ac40 5670MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5500MHz Ant0



Freq. Stability NVNT ax20 5580MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5700MHz Ant0



Freq. Stability NVNT ax40 5510MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax40 5550MHz Ant0



Freq. Stability NVNT ax40 5670MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	ac20	5500	Ant1	5500	0	0	25	Pass
NVNT	ac20	5580	Ant1	5580	0	0	25	Pass
NVNT	ac20	5700	Ant1	5700	0	0	25	Pass
NVNT	ac40	5510	Ant1	5509.96	-40000	-7.26	25	Pass
NVNT	ac40	5550	Ant1	5549.96	-40000	-7.21	25	Pass
NVNT	ac40	5670	Ant1	5670	0	0	25	Pass
NVNT	ax20	5500	Ant1	5500	0	0	25	Pass
NVNT	ax20	5580	Ant1	5580	0	0	25	Pass
NVNT	ax20	5700	Ant1	5700	0	0	25	Pass
NVNT	ax40	5510	Ant1	5510	0	0	25	Pass
NVNT	ax40	5550	Ant1	5549.96	-40000	-7.21	25	Pass
NVNT	ax40	5670	Ant1	5669.96	-40000	-7.05	25	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Freq. Stability NVNT ac20 5500MHz Ant1



Freq. Stability NVNT ac20 5580MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5700MHz Ant1



Freq. Stability NVNT ac40 5510MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac40 5550MHz Ant1



Freq. Stability NVNT ac40 5670MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5500MHz Ant1



Freq. Stability NVNT ax20 5580MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5700MHz Ant1



Freq. Stability NVNT ax40 5510MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax40 5550MHz Ant1



Freq. Stability NVNT ax40 5670MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



E.6 Duty Cycle

Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5500	Ant0	96.87	0.14	0.72
NVNT	a	5580	Ant0	96.94	0.13	0.72
NVNT	a	5700	Ant0	96.94	0.13	0.72
NVNT	n20	5500	Ant0	96.73	0.14	0.77
NVNT	n20	5580	Ant0	96.65	0.15	0.77
NVNT	n20	5700	Ant0	96.73	0.14	0.77
NVNT	n40	5510	Ant0	93.64	0.29	1.54
NVNT	n40	5550	Ant0	93.64	0.29	1.54
NVNT	n40	5670	Ant0	93.64	0.29	1.54
NVNT	ac20	5500	Ant0	96.76	0.14	0.76
NVNT	ac20	5580	Ant0	96.76	0.14	0.76
NVNT	ac20	5700	Ant0	96.76	0.14	0.76
NVNT	ac40	5510	Ant0	93.82	0.28	1.53
NVNT	ac40	5550	Ant0	93.68	0.28	1.53
NVNT	ac40	5670	Ant0	93.68	0.28	1.53
NVNT	ax20	5500	Ant0	96.76	0.14	0.76
NVNT	ax20	5580	Ant0	96.76	0.14	0.76
NVNT	ax20	5700	Ant0	96.76	0.14	0.76
NVNT	ax40	5510	Ant0	93.82	0.28	1.53
NVNT	ax40	5550	Ant0	93.68	0.28	1.53
NVNT	ax40	5670	Ant0	93.69	0.28	1.53



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Duty Cycle NVNT a 5500MHz Ant0



Duty Cycle NVNT a 5580MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Duty Cycle NVNT a 5700MHz Ant0



Test Graphs

Duty Cycle NVNT n20 5500MHz Ant0



Duty Cycle NVNT n20 5580MHz Ant0




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT n40 5550MHz Ant0



Duty Cycle NVNT n40 5670MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac20 5500MHz Ant0



Duty Cycle NVNT ac20 5580MHz Ant0





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac40 5550MHz Ant0



Duty Cycle NVNT ac40 5670MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5500MHz Ant0



Duty Cycle NVNT ax20 5580MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5700MHz Ant0



Duty Cycle NVNT ax40 5510MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax40 5550MHz Ant0



Duty Cycle NVNT ax40 5670MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)	1/T (kHz)
NVNT	a	5500	Ant1	96.94	0.13	0.72
NVNT	a	5580	Ant1	96.94	0.13	0.72
NVNT	a	5700	Ant1	96.94	0.13	0.72
NVNT	n20	5500	Ant1	96.7	0.15	0.78
NVNT	n20	5580	Ant1	96.7	0.15	0.78
NVNT	n20	5700	Ant1	96.62	0.15	0.78
NVNT	n40	5510	Ant1	93.54	0.29	1.57
NVNT	n40	5550	Ant1	93.53	0.29	1.57
NVNT	n40	5670	Ant1	93.53	0.29	1.57
NVNT	ac20	5500	Ant1	96.76	0.14	0.76
NVNT	ac20	5580	Ant1	96.68	0.15	0.76
NVNT	ac20	5700	Ant1	96.76	0.14	0.76
NVNT	ac40	5510	Ant1	93.69	0.28	1.53
NVNT	ac40	5550	Ant1	93.68	0.28	1.53
NVNT	ac40	5670	Ant1	93.82	0.28	1.53
NVNT	ax20	5500	Ant1	96.68	0.15	0.76
NVNT	ax20	5580	Ant1	96.76	0.14	0.76
NVNT	ax20	5700	Ant1	96.76	0.14	0.76
NVNT	ax40	5510	Ant1	93.69	0.28	1.53
NVNT	ax40	5550	Ant1	93.68	0.28	1.53
NVNT	ax40	5670	Ant1	93.68	0.28	1.53



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Duty Cycle NVNT a 5500MHz Ant1



Duty Cycle NVNT a 5580MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT a 5700MHz Ant1



Duty Cycle NVNT n20 5500MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT n20 5580MHz Ant1



Duty Cycle NVNT n20 5700MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT n40 5510MHz Ant1



Duty Cycle NVNT n40 5550MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT n40 5670MHz Ant1



Duty Cycle NVNT ac20 5500MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac20 5580MHz Ant1



Duty Cycle NVNT ac20 5700MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac40 5510MHz Ant1



Duty Cycle NVNT ac40 5550MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ac40 5670MHz Ant1



Duty Cycle NVNT ax20 5500MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax20 5580MHz Ant1



Duty Cycle NVNT ax20 5700MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Duty Cycle NVNT ax40 5510MHz Ant1



Duty Cycle NVNT ax40 5550MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity