
FCC TEST REPORT Report No.: FR502506

4.7 Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 FCC ID
 : RSE-ST780

 TEL: 886-2-2696-2468
 Page No.
 : 30 of 56

 FAX: 886-2-2696-2255
 Issued Date
 : Dec. 1, 2005

FCC TEST REPORT Report No.: FR5O2506



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : RSE-ST780


 TEL: 886-2-2696-2468
 Page No.
 : 31 of 56

 FAX: 886-2-2696-2255
 Issued Date
 : Dec. 1, 2005

FCC TEST REPORT Report No.: FR502506

4.9 Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW

REAR VIEW

 SPORTON International Inc.
 FCC ID
 : RSE-ST780

 TEL: 886-2-2696-2468
 Page No.
 : 50 of 56

 FAX: 886-2-2696-2255
 Issued Date
 : Dec. 1, 2005