## HP Inc.

3390 East Harmony Road

Fort Collins 80528 Colorado United States

Federal Communications Commission 7435 Oakland Mills Road - Gate A Columbia, Maryland 21046

Date: June 27, 2019

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: B94-AX201D2WR

To the Commission:

This Change of Identification request applies for a **new** FCC ID: B94-AX201D2WR as established in 47CFR 2.933(b) for a currently approved device. This application by **HP Inc.** will establish a new FCC ID under **B94** grantee code for purpose of marketing. The original grant to **PD9AX201D2** will remain in effect.

An authorization letter by **Intel Mobile Communications** is attached. Per 2.933(b)

- 1. The original identification is **PD9AX201D2**
- 2. The original grant date is 11/20/2018
- 3. The equipment is electrically identical. Only the FCC ID number is different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

**Cover Letter** 

**External Photos** 

FCC ID label format and location

Sincerely yours,

Name: Peter S. Tevlin	Email: peter.tevlin@hp.com Telephone: +1 512 319 7260
Signature:	Peter S. Turkin

Title: Regulatory Manager, Communications Modules, Worldwide Technical Regulations

On behalf of Company: HP Inc. 1501 Page Mill Road Palo Alto, CA 94304