1. Please note that while you have provided a block diagram for the PCS and Cell you have not provided the block diagram of the Bluetooth. Please provide a block diagram of the Bluetooth transmitter section giving the frequencies and their paths.

Uploaded.

- 2. Please note that I did not see the Bluetooth schematics provided for this device. Please provide the BT schematics.

  Uploaded.
- 3. Please note that this is a part 15 device as well as a licensed device. As such, all of the pertinent part 15 statements are required. Your manual states, Unauthorized antennas, modifications, or attachments could damage the device and may violate regulations governing radio devices." Please note that the caution is to inform the user that these unauthorized modifications may void the users authority to operate the equipment not just that they may violate the regulations. Please clarify the statement.

The language in the draft user guide contains the exact wording approved by the FCC and other TCBs for numerous previous phones. The wording provided meets the substance of Part 15 while also being technically accurate and is consistent with that provided for our other products.

4. Please note that this is a part 15 device as well as a licensed device. Please note that 15.19(a)(3) states, All other devices shall bear the following statement in a conspicuous location on the device:

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

As this device is small, this statement can be in the manual. Please provide the precise statement in the manual as required by part 15.19(a)(3) above. See 3.

5. Please note that the test reference and summary data in the GSM850 report states part 24 (see pages 4, 8, 17, 21, 27 and 29 of the 850GSM report). As this is for the 800MHz cell band, please refer to the correct rule parts in the respective reports.

Corrected test report has been uploaded.