



HERMON LABORATORIES

August 22, 2005

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated August 19, 2005; Telematics Wireless Ltd.
FCC ID:NTAFP300RA, ATCB002645

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The User Manual was corrected, "User_manual_16547_rev2" was uploaded on August 22, 2005.
- 2) The measured power of 31.2 dBm is maximum output power. The revised file "Tune_up_procedure_16547_rev2" was uploaded on August 22, 2005.

Many thanks for your support and attention in all matters.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories