



Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526 -4100
<http://www.cisco.com>


Exhibit : Internal Photos

Model Number: CP-DX80

FCC ID: LDKDX800956


IC: 2461B - DX800956

CP-DX80 : Internal PCB Mother Board (top view)




EDCS-1118876

CP-DX80 : Internal PCB Mother Board (Connector view)




CP-DX80 : Internal PCB Mother Board (Radio Section with Shield removed)




Radio Section


CP-DX80 : Internal PCB Mother Board (Top 1/3) close up view




CP-DX80 : Internal PCB Mother Board (Top 2/3) close up view



CP-DX80 : Internal PCB Mother Board (Top 3/3) close up view



CP-DX80 : Internal PCB Mother Board (bottom view)



CP-DX80 : Internal PCB Mother Board (bottom 1/3) Close up view

