



Testsetup below 1 GHz




Testsetup below 1 GHz




G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-

Testsetup below 1 GHz




Testsetup below 1 GHz




G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-

Testsetup below 1 GHz





Testsetup above 1 GHz



G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-




G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-

Testsetup above 1 GHz




Testsetup above 1 GHz




G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-

Testsetup below 1 GHz




Testsetup below 1 GHz




G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-

Testsetup below 1 GHz




Testsetup below 1 GHz




G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-

Testsetup below 1 GHz




Testsetup above 1 GHz




G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-

Testsetup above 1 GHz



Testsetup above 1 GHz



G0M-2209-1656

Test Report No.: G0M-2209-1656-TFC247BTBR-