

May 6, 2019

Timco Engineering, Inc.
849 NW State Road 45
P.O. Box 370
Newberry, Florida 32669

Re: Justification for Label Location


FCC: 2AD9X-KFG

IC: 12637A-KFG

To Whom It May Concern:

Per our label location exhibit, we will place our label on the inside of the housing Lid. The outside of the small sensor housing would degrade the appearance of the sensor. The inside of the Lid is easily accessible and visible when accessing the battery.

Sincerely,



Justin Carlson
General Manager
Versa Wireless Inc.
103 - 19292 60th Avenue
Surrey, BC V3S 3M2
Canada