



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

February 25, 2005

RE: Schulmerich Carillons, Inc.

IC Number: RXR0362024000

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide close up photographs of the RF board (top and bottom) portion of the device.
- 2) It appears the frequency on the 731 and RSP forms should be adjusted to 908.90 – 911.90 MHz. Please verify and adjust as necessary.
- 3) Also, on the base station, it appears the frequency should be adjusted to 908.40 – 911.4 MHz on the 731 and RSP forms. Please adjust.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.