

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)



FCC ID: PQN91763M012G4



INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)



FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)



FCC ID: PQN91763M012G4



INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Equipment Photographs

Model : 91764

(Internal)



Equipment Photographs


FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Model : 91764

(Internal)



Equipment Photographs



FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

Model : 91764

(Internal)



Equipment Photographs



Model : 91764

FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

(Internal)



Equipment Photographs



Model : 91764

FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

(Internal)



Equipment Photographs



Model : 91764

(Internal)

FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001



Equipment Photographs



Model : 91764

(Internal)

FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001




Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001




Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001




Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001



Equipment Photographs

Model : 91764

(Internal)

Report No.: 15020700HKG-001

Report No.: 15020700HKG-001





Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001



Equipment Photographs



Model : 91764

(Internal)

FCC ID: PQN91763M012G4

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001




Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001





Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001



Equipment Photographs

Model : 91764

(Internal)

INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001



FCC ID: PQN91763M012G4