

TELEPHONE: (352) 472-5500 (888) 472-2424 FAX: (352) 472-2030 E-MAIL: <u>info@timcoengr.com</u> WEBSITE: www.timcoengr.com

October 28, 1999

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

## SUBJECT: RADIOSHACK, A DIVISION OF TANDY CORP. FCC ID: AA02101822

REFERENCE: CONFIRMATION #: EA95712

To Whom It May Concern:

We submitted the application for certification for the above mentioned application on October 19, 1999. After submitting the application, it was brought to my attention that we had made an error on the output power that we put on the 731 form.

This letter is a request to correct the 731 form. The output power should read .30 Watts.

Regards,

Sharon A. Hoffman/TIMCO ENGINEERING, INC.