

From Group		To 99999	From Item	OLUSB To OLUSB	Facility	GA	Sort By	ITEM	Cu st No.					
Level	Item	Description	Group	Qty	Reqd.	U/M	Cl s	L/T	Effect.	Discon.	Schema	Alt A.	Qty	Op#
-----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----
Parent	OLUSB	OLYMPIA USB DONGLE	TG			EA	FG	15						999
	1 OLUSBB	USB DONGLE UNIT (ALL)	SA	1	EA	SA	0	7/16/02	99/99/99					
	0.2 OLUSBBC	USB DONGLE CASING (ALL)	SA	1	EA	SA	0	7/16/02	99/99/99					
...3	OLUSBBCXXX	USB DONGLE CASING COMMON	SA	1	EA	SA	0	7/16/02	99/99/99					
...4	KEM-P9051	MIDDLE TOP	MD	1	EA	RM	999	7/16/02	99/99/99					
...4	KEM-P9052	MIDDLE BOTTOM	MD	1	EA	RM	999	7/16/02	99/99/99					
...4	KEM-P9053	SIDE	MD	2	EA	RM	999	7/16/02	99/99/99					
...4	KEM-P9054	LENS	MD	1	EA	RM	999	7/16/02	99/99/99					
	0.2 OLUSBM	OLUSB MAIN PCB	SA	1	EA	SA	0	7/16/02	99/99/99					999
...3	OLUSBMXXX	OLUSB MAIN PCB COMMON	SA	1	EA	SA	0	02-07-08	99/99/99					999
...4	KCAN-001	ANT SMD ECAN0602T2450 KAMII	EQ	1	EA	RM	60	02-04-07	99/99/99	ANT1				999
...4	KCC-129FRCNPOG	CAP. CER. CHIP 50V CH C% 12PF	EA	1	EA	RM	120	9/25/02	99/99/99	C6				
										E: E505				
...4	KCD-L08B-KB	LED CHIP BLUE KINGBRIGHTKPA-3010QBC-C	EJ	1	EA	RM	90	02-04-07	99/99/99	D1				999
...4	KEOE-0T462	USB CABLE FOR OLUSB 10MM	EQ	1	EA	RM	60	02-04-07	99/99/99	J1				
...4	OLUSBMS	OLUSB MAIN PCB SMT	SA	1	EA	SA	6	02-07-08	99/99/99					999
...5	KCC-T107DCM	CAP. TANT. CHIP 10V M 100UF 6032	EA	1	EA	RM	60	7/24/02	99/99/99	C3				
										E: 501				
...5	KCC-T476CBM	CAP. TANT. CHIP 6.3V M 47UF 3528	EA	2	EA	RM	60	7/24/02	99/99/99	C2,C9				999
										E: 501				
...5	KCC-100FDNPOMUG	CAP.CER.CHIP 50V D% 10PF NPO MURATA	EA	5	EA	RM	90	9/26/02	99/99/99	C1,C4,C7,C8,C5				0
										E: E505				
...5	KCC-103DRKBG	CAP. CER. CHIP 16V B K% 0.1UF	EA	1	EA	RM	120	9/26/02	99/99/99	C10				
										E: E505				
...5	KCC-104DZFMUG	CAP.CER.CHIP 16V F Z% 0.1UF MURATA	EA	3	EA	RM	42	9/26/02	99/99/99	C13,C11,C12				0
										E: E503,505				
...5	KCR-102G	RES. CHIP 1/16W 1K	EC	1	EA	RM	90	9/26/02	99/99/99	R1				999
										E: E505				
...5	KCR-103G	RES. CHIP 1/16W 10K	EC	1	EA	RM	90	9/26/02	99/99/99	R6				999
										E: E505				
...5	KCR-561G-JN4SA	RES CHIP 1/16W 5% 560 OHM SAMSUNG	EC	1	EA	RM	60	9/26/02	99/99/99	R5				0
										E: E505				
...5	KCT-2SA1162GR	TR. CHIP PNP 2SA1162GR-TE85R	ED	1	EA	RM	130	02-04-07	99/99/99	Q1				999
...5	KEIC-XC6201T332	IC XC6201T332PR 3.3V REGULATOR SOT-89	EL	2	EA	RM	90	02-04-07	99/99/99	U2,U3				999
...5	KEPC-630-02	PCB OLUSB MAIN 43X25MM 4LAYE	ES	1	EA	RM	999	02-04-07	99/99/99					
	0.2 OLUSBR	OLUSB RF MODULE PCB	SA	1	EA	SA	0	7/16/02	99/99/99					999
...3	OLUSBRXXX	OLUSB RF MODULE PCB COMMON	SA	1	EA	SA	0	02-07-08	99/99/99					999
...4	KEM-M9052	SHIELD CAN COVER	MA	1	EA	RM	999	7/16/02	99/99/99					
...4	OLUSBR5	OLUSB RF MODULE PCB SMT	SA	1	EA	SA	6	02-07-08	99/99/99					999
...5	KCC-100FDNPOMUG	CAP.CER.CHIP 50V D% 10PF NPO MURATA	EA	3	EA	RM	90	9/25/02	99/99/99	C12,C25,C28				0
										E504				
...5	KCC-101FJNPOMUG	CAP.CER.CHIP 50V CH J% 100PF MURATA	EA	1	EA	RM	42	9/25/02	99/99/99	C21				0
										E504				
...5	KCC-103ERKBG	CAP. CER. CHIP 25V B K% 10NF	EA	4	EA	RM	120	9/25/02	99/99/99	C10,C13,C29,C32				0
										E504				
...5	KCC-104DZFMUG	CAP.CER.CHIP 16V F Z% 0.1UF MURATA	EA	5	EA	RM	42	9/25/02	99/99/99	C16,C17,C26,C18,C27				0
										E504				
...5	KCC-150FJNPOGNG	CAP. CER. CHIP 50V 5% NPO 15P 0402	EA	4	EA	RM	60	9/26/02	99/99/99	C1,C2,C3,C23				0
										E: E504,506				

Elect. checked by _____ Mech. Checked by _____ Software checked by _____ Approved by _____

From Group 6B6	To 99999	From Item	OLUSB To OLUSB	Facility GA	Sort By ITEM	Cu st No.							
Level	Item	Description	Group	Qty	Reqd.	U/M	CI	s	L/T	Effect.	Discon.	Schema	Alt A.Qty Op#
-----	----	-----	-----	-----	-----	---	---	---	---	-----	-----	-----	--- -- --
....5	KCC-159FBCGGNG	CAP. CHIP 50V B COG 1.5P 0402	EA			4 EA	RM			60 9/26/02	99/99/99	C30,C31,C15,C20 E:E206	0
....5	KCC-200FJNPOMUG	CAP. CER. CHIP 50V CH J% 20PF MURATA	EA			2 EA	RM			42 9/25/02	99/99/99	C5,C19 E:E504	0
....5	KCC-221FJCOGMUB	CAP CER CHIP 50V COG J 220PF	EA			1 EA	RM			999 9/25/02	99/99/99	C7 E:E503,504	
....5	KCC-225DZY5VGNM	CAP. CER. CHIP 16V 2.2UF Y5V 0805	EA			2 EA	RM			60 9/25/02	99/99/99	C14,C8 E:E504	0
....5	KCC-229FBCGGNG	CAP. CHIP 50V B COG 2.2P 0402	EA			1 EA	RM			60 02-04-07	99/99/99	C24	0
....5	KCC-339FRCNPOG	CAP. CER. CHIP 50V CH C% 3P3F	EA			1 EA	RM			120 02-04-07	99/99/99	C11	0
....5	KCC-470FJNPOMUG	CAP CER CHIP 50V NPO J%47PF MURATA	EA			1 EA	RM			999 02-04-07	99/99/99	C9	0
....5	KCL-220MU-5JLG	IND CHIP 22NH +/-2% LQP10A22NG00	EO			1 EA	RM			999 9/25/02	99/99/99	L8 E:E504	0
....5	KCL-270MU-5JLG	IND CHIP 27NH +/-2% LQP10A27NG00	EO			1 EA	RM			90 7/16/02	99/99/99	L12	0
....5	KCL-279MU-5JBG	IND CHIP 2.7NH +/-0.1NHLQP10A2N7B00	EO			1 EA	RM			90 9/25/02	99/99/99	L10 E:E504	0
....5	KCL-399MU-5JBG	IND CHIP 3.9NH +/-0.1NH LQP10A3N9B00	EO			3 EA	RM			90 02-04-07	99/99/99	L1,L14,L15	0
....5	KCL-479MU-5JBG	IND CHIP 4.7NH +/-0.1NH LQP10A4N7B00	EO			1 EA	RM			90 02-04-07	99/99/99	L11	0
....5	KCL-519MU-5JBG	IND CHIP 5.1NH +/-0.1NH LQP10ASN1B00	EO			1 EA	RM			999 9/25/02	99/99/99	L9 E:E504	0
....5	KCR-000G	RES. CHIP 1/16W 0 OHM	EC			2 EA	RM			60 02-04-07	99/99/99	R3,R6	999
....5	KCR-184G-JN4YA	RES. CHIP 1/16W 5% 180K 0402	EC			1 EA	RM			42 02-04-07	99/99/99	R2	0
....5	KCR-204G-JN4YA	RES. CHIP 1/16W 5% 200K 0402	EC			1 EA	RM			999 9/25/02	99/99/99	R10 E:E504	999
....5	KCR-209G-JN4GN	RES. CHIP 1/16W 5% 2 040	EC			1 EA	RM			60 9/25/02	99/99/99	R1 E:E504	0
....5	KCR-220G-JN4GN	RES. CHIP 1/16W 5% 22 0402	EC			3 EA	RM			60 02-04-07	99/99/99	R4,R5,R8	0
....5	KCR-753G-JN4YA	RES. CHIP 1/16W 5% 75K 0402	EC			1 EA	RM			999 9/25/02	99/99/99	R9 E:E504	999
....5	KCTR-005-TD	BALUM 2.4G TDK HHM-1517	EZ			1 EA	RM			60 02-04-07	99/99/99	U13	999
....5	KCX-0009	CRYSTAL SMD 16MHZ TSX-10 TOYOCOM	E2			1 EA	RM			75 02-04-07	99/99/99	X1	0
....5	KECF-0158	BPF 2.45G SOSHIN MDR741F	EI			1 EA	RM			75 02-04-07	99/99/99	U3	999
....5	KEIC-AS179-92	IC SPDT SWITCH 3GHZ ALPHA AS179-92	EL			1 EA	RM			90 02-04-07	99/99/99	U5	999
....5	KEIC-BC212015B	IC CHIP BC212015BDN-E4-0112 CSR	EL			1 EA	RM			90 02-04-07	99/99/99	U1	999
....5	KEIC-M29W800DB7	IC 8M ST M29W800DB70ZA6F.MB70ZA6	EL			1 EA	RM			999 02-05-09	99/99/99	U2 E:E503,504	
....5	KEIC-M29W800AB9	IC 8M ST M29W800AB90ZA6F.M	EL			0 EA	RM			999 9/25/02	99/99/99	E:E503	*
....5	KEIC-XC6204B	IC LDO REGULATOR 1.8V TOREX XC6204B182MR	EL			1 EA	RM			90 02-04-07	99/99/99	U4	999
....5	KEIC-XF2400PJ	IC PA 2.4G MURATA XF2400PJ-SF0701	EL			1 EA	RM			999 9/25/02	99/99/99	U6 E:E504	0
....5	KEIC-XM2400LB	IC LNA 2.4G MURATA XM2400LB=PM0601	EL			1 EA	RM			90 02-04-07	99/99/99	U7	999
....5	KEM-M9051	SHIELD CAN BASE	MA			1 EA	RM			999 7/16/02	99/99/99		
....5	KEPC-632-05	PCB BC02 CLASS1 16.5X32MM 4LAYER	ES			1 EA	RM			999 9/25/02	99/99/99	E:E504	

Th e Latest ECN No. is : 505

Elect. checked by _____ Mech. Checked by _____ Software checked by _____ Approved by _____

>>>>End of B.O.M.<<<<