



Competence Certainty Quality

BABT
Balfour House, Churchfield Road
Walton on Thames
Surrey, KT12 4TD
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201

Ref: US000112

5th December 2005

To FCC

Direct Dial: +44 (0)1932 251230 E-mail: Tom.Twynam@babt.com Website: www.babt.com

Evaluation of Symbol Bluetooth Module LMX5452 FCC id: H9PLMX5452

I have assessed the above referenced submission for the Symbol Bluetooth Module and found it to be compliant.

The following were noted and resolved during the evaluation.

Managing Director:

1: Covering Letters

The application was originally addressed to the TCB at Claremont House, Hersham, but this has been redirected to BABT TCB in Balfour House, Walton on Thames. Following communication from the applicant's agent, BABT have agreed to construe all references to BABT at Claremont House as references to the TCB functions of BABT at Balfour House.

2. RF Exposure

It was clarified that the module was not tested in a generic host for the purposes of RF exposure compliance. This means that tests must be performed on all hosts in which the product is installed. A suitable note will be placed in the grant conditions.

Yours sincerely

Tom Twynam Technical Certifier For BABT TCB

7 1 Tuymam

British Approvals Board for Telecommunications TÜV SÜD Group