## Ningbo Fulman Communication Technology Co., Ltd

9/9/2022

## Dear Sirs:

We hereby declare that because the earphone size is too small, the FCC ID number is printed on the User Manual, hereby declare.

FCC ID: 2A7Z4-NBF

## Declaration on toxic or hazardous substances and elements contained in electronic products

Component name	Hazardous and harmful substances or elements					
	Lead (Pb)	Mercury (Hg)	Cadmium (Cd)	hexavalent chromium (Cr VI)	Polybrominated biphenyls (PBB)	Polybrominated diphenyl ethers (PBDE)
PCB	X	0	0	0	0	0
Ceramic components	X	0	0	0	0	0
IC components	X	0	0	0	0	0
Charging cable	0	0	0	0	0	0
Casing	0	0	0	0	0	0

- This form has been wrote in accordance with SJ/T11364.
- O : It means that the content of hazardous and harmful substances or elements in all homogeneous materials of the component is below the limit requirements in GB/T26572 standard.
  X : It indicates that the content of the toxic substance or element in at least one
- X : It indicates that the content of the toxic substance or element in at least one homogeneous material of the component exceeds the limit requirements in GB/T26572 standard.

## FCC Warning

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

NOTE 1: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio ortelevision reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

NOTE 2: Any changes or modifications to this unit not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

The device has been evaluated to meet general RF exposure requirement. The device can be used in portable exposure condition without restriction.

FCC ID: 2A7Z4-NBF

Sincerely,

Signature: June Shen
Name: Lingyun Shen

Title: General manage

Company: Ningbo Fulman Communication Technology Co., Ltd