



Intertek Testing Services

ETL SEMKO

Report No.: 0006710

Mode: Charging

Tested By: Hong, Report No.: 0006710

Scan Settings (1 Range)

Frequencies: Receiver Settings
Start Stop IF BW Detector M-Time Atten Preamp OpRge
450K 30M 5K 10K PK 20ms AUTO LN OFF 60dB


Final Measurement x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No Start Stop Name
21 9K 30M EY06938



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0006710

Tested By: Hong, Report No.: 0006710

Scan Settings (1 Range)

Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450K	30M	5K	10K	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

no Results

Mode: Charging

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0006710

Made : Standby

Tested By:Hong, Report No.:0006710

Scan Settings (1 Range)

Frequencies:

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRng
450K	30M	5K	10K	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x CP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

Z1 9K 30M EWD693



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0006710

Made : Standby

Tested By: Hong, Report No.: 0006710

Scan Settings (f Range)

----- Frequencies -----		----- Receiver Settings -----	
Start	Stop	Step	IF BW Detector M-Time Atten Preamp OpRge
450k	30M	5k	10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

no Results

Ctrl No.: N/A



Intertek Testing Services
ETL SEMKO

Report No.: 0006710

Model : Transmission

Tested By:Hong, Report No.:0006710

Scan Settings (1 Range)

Frequencies (1 Range)

Receiver Settings

Start Stop Step IF BW Detector M-Time Atten Preamp OpRng

450K 30M 5K 10K PK 20ms AUTO LN OFF 60dB

Final Measurement x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9K 30M EW0595



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0006710

Tested By: Hong, Report No.:0006710

Scan Settings (1 Range)

Mode : Transmission

----- Frequencies ----- Receiver Settings -----
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

no Results

Ctrl No.: N/A